

REGISTERED LAND SURVEYOR'S INSPECTION
PLAT AND CERTIFICATE FOR MORTGAGE
LOAN PURPOSE

COLLINS LAND SURVEYING, INC.

3340 W. 151st ST. S. - P.O. Box 250

KIEFER, OK. 74041

OFFICE (918)321-9400 FAX (918)321-9404

J.O. NO.: 17-05-132

First American Title
Customer: & Trust Company

Borrower: McCleary, Lois R.
2241736-TU02

Plat No: 3293

B/L=Building Line
U/E=Utility Esmt.
F/E=Fence Esmt.


OB/L-Out Building Line
SW/E=Sidewalk Esmt.
R/W=Right of Way

D/E=Drainage Esmt.
B/E=Buried Tele. & Elec. Cable Esmt.
S/E=Service Entrance

SCALE: 1"=30'



SUBJECT PROPERTY LIES WITHIN FLOOD ZONE "UNSHADED X" AN AREA OF MINIMAL FLOOD HAZARD AS SHOWN ON FIRM MAP#400236 0456L, DATED 10/16/2012.



THIS PLAT IS MADE FOR AND AT THE REQUEST OF: First American Title & Trust Company /

Gateway Mortgage Group, LLC, ISAOA/ATIMA

FOR MORTGAGE LOAN PURPOSES ONLY COVERING LEGAL DESCRIPTION AS PROVIDED

Lot Forty-eight (48), Block Two (2), COUNTRY CLUB ESTATES
ADDITION to the City of Broken Arrow, Tulsa County, State of
Oklahoma, according to the recorded Plat No. 3293.

Property address: 8202 South Ash Avenue, Broken Arrow, Oklahoma

SURVEYORS STATEMENT