SURPLUS VEHICLES AND EQUIPMENT

UPDATED 5-11-2016

UNIT#	ASSET #	VIN#	DEPARTMENT	DESCRIPTION	REASON FOR DISPOSAL
0059	00000397	2FAFP71W0YX213163	Police	2000 Ford Crown Victoria	Replaced, Engine needs major repairs
0149	00003368	2FAFP71W91X166575	Police	2001 Ford Crown Victoria	Replaced, Vehicle was operational when removed from service
0230	00003584	1B3EL46R92N264240	Police	2002 Dodge Stratus	Engine needs rebuilt, overheated
0346	00003746	2FAFP71W33X198400	Police	2003 Ford Crown Victoria	Needs both catalytic convertors, paint peel on body
0350	00003751	2FAFP71W03X199404	Police	2003 Ford Crown Victoria	Engine dies and costo of repairs exceeds vehicles worth
0348	00003749	2FAFP71W73X199402	Police	2003 Ford Crown Victoria	Transmission needs rebuilt, paint peel
0431	00004268	2FAFP71W34X151901	Police	2004 Ford Crown Victoria	Due for replacement. Needs brakes, radiator fan, module
0433	00004270	2FAFP71W14X151900	Police	2004 Ford Crown Victoria	Power steering issues and rack and pinion needs replaced
0578	00004500	2FAFP71W45X176257	Police	2005 Ford Crown Victoria	ABS light, check engine light. Dept. Declined repairs
0587	00004511	2FAFP71WX5X176263	Police	2005 Ford Crown Victoria	Needs transmission rebuilt
0588	00004508	2FAFP71W15X176264	Police	2005 Ford Crown Victoria	Totaled in accident
0646	00004747	2FAFP71W96X157964	Police	2006 Ford Crown Victoria 1998 Ford Windstar Van	Transmission needs rebuilt, paint peel
9825 0706	00002583	2FTZA54U3WBE19319	Police Police	2007 Chevrolet Impala	Transmission needs rebuilt and fuel module. Cranks, but no start
	00004866	2G1WB58K179292404		2007 Chevrolet Impaia 2007 Ford Crown Victoria	Damage to front end from accident
0740	00004896	2FAFP71W57X145649	Police	2007 Ford Crown Victoria	Engine needs tune up, transmission slips, paint peel, minor tears in upholstery
0027	00003045	1FMPU16L7YLB67651	Fire Dept.	2000 Ford Expedition	Replaced. Needs battery. Has electrical drain. Carpet has tears and holes.
0027	n/a	n/a	Fire Dept.	Rice hose test machine (qty.2)	Obsolete
	n/a	n/a	Fire Dept.	Chief floating fire pump	Obsolete
	n/a	n/a	Fire Dept.	Reelcraft 30000 hose reel (qty.2)	Obsolete
	II/a	II/ a	гие Бері.	Reelcraft 30000 flose feet (qty.2)	Obsolete
008	00002120	1FMCA11U25Z	General Government/Court Clerk	2000 Ford Aerostar XLT	Cost for repairs exceed vehicle worth
	00002120	2023332	General Government/I.S. Dept		Replaced on 8-23-13 Unit was operational when removed from service
GENTINE	n/a	n/a	General Government/City Hall	Plastic office chairs (qty.6)	Replaced
	n/a	n/a	General Government/City Hall	Office chair (qty. 5)	Replaced
	00008195	n/a	General Government/City Hall	Digital wall display	Replaced
	n/a	n/a	General Government/City Hall	Church Pew (qty 3)	Demo from Church
	n/a	n/a	General Government/City Hall	Brick (qty 65)	Demo from Church
	00008148	4730126	General Government/City Hall	Mail Postage envelopment machine	
	00000140	+130120	Cancian Government/City Fidil	1 come curciopinent macilin	Constitution
1038	NONE	L6/2/2005-00006	Stormwater	2010 Campbell Hausfeld air comp	Froine will not run
0354	00003755	1GTEC14V33Z283860	Stormwater	2003 GMC Pick up	Transmission. Slips between shifts and excessive noise
0354	00003753	1GTEC14V93Z287279	Stormwater	2003 GMC Pick up	Repair cost exceed vehicles worth. Transmission needs rebuilt
0330	00003737	TOTECT4 V / SELECTET /	Stormwater	2005 GMC Fick up	Repair cost exceed veincies worth. Transmission needs result
094	00000911	A1192938	Water Utilities	Portable welder (Attached to 9802	Replaced
9725	00000311	1FTDF1769VKC77483	Water Utilities	1997 Ford F-150	Engine Noise. Dept. decided not to repair because of cost and age of vehicle
9768	NONE	R15131420	Water Utilities	Compressor (Attached to 9802)	Replaced
263	00000882	11091	Water Utilities	Belshe Equipment trailer Tandum	
262	00000706	11089	Water Utilities		Replaced Need new axle and tires
276	00001258	16JFO162XN1022733	Water Utilities	Belshe Equipment Trailer Tandum	*
0023	00003038	1B7GL22X2YS738006	Water Utilities	2000 Dodge Dakota	Engine overheated, power train control module needs replaced
0002	00003037	95342412	Sewer Utilities	2000 Snapper riding mower	Engine needs repair
	n/a	n/a	Sewer Utilities	Cues sewer line camera	Obsolete
9723	00002407	1FTEF1766VKC67174	Street Dept.	1997 Ford F-150	Replaced. Repair cost are greater than vehicles worth
0237	00003658	1D7HA16N7ZJ224667	Street Dept.	2002 Dodge 1500 Pickup	Replaced. Needs transmission rebuilt
0356	00003757	1GTEC14V93Z287279	Street Dept.	2003 Dodge 1500 Pickup	Transmission slips, throttle body and MAF sensor, water pump A/C blower motor
NONE	NONE		Street Dept.	Service bed replaced on a Ford F-3	Replaced
9811	00002558	22566	Street Dept.	Valk Plow	Replaced
0207	00003559	26485	Street Dept.	Valk Plow	Replaced
0327	00003695	27464	Street Dept.	Valk Plow	Replaced
0127	00003356	25603	Street Dept.	Valk Plow	Replaced
0208	00003560	26483	Street Dept.	Valk Plow	Replaced
0328	00003690	27465	Street Dept.	Valk Plow	Replaced
9810	00002559	22565	Street Dept.	Valk Plow	Replaced
0335	00003699	3018378	Street Dept.	Monroe Sander	Replaced
0336	00003700	3018380	Street Dept.	Monroe Sander	Replaced
0337	00003701	3018379	Street Dept.	Monroe Sander	Replaced
03112	00004191	SC14986	Street Dept.	Warren Sander	Replaced
03113	00004192	SC14987	Street Dept.	Warren Sander	Replaced
0212	000002710	111TENTE A A D 2010 20 == :	Contract		
0313	00003719	1HTWHAAR63J068794	Nanitation		
0507					Due for replacement. Engine needs overhaul
0825	00004403	1HTWGAAR75J152371	Sanitation	2005 International/ Leach 2RIII ref	Due for replacement. Damage to front grill area
	00004403 00005223				Due for replacement. Damage to front grill area
0106	00005223	1HTWGAAR75J152371 2FZHAWBS78AZ88365	Sanitation Sanitation	2005 International/ Leach 2RIII ref 2008 Freightliner/McNeilus refuse	Due for replacement. Damage to front grill area Cab electrical fire
0106	00005223 00003083	1HTWGAAR75J152371 2FZHAWBS78AZ88365 1B7HC16Y215771465	Sanitation Sanitation Fleet Maintenance	2005 International/ Leach 2RIII ret 2008 Freightliner/McNeilus refuse 2001 Dodge Ram 1500	Due for replacement. Damage to front grill area Cab electrical fire Cost of repairs are higher than vehicles value
0888	00005223 00003083 00005389	1HTWGAAR75J152371 2FZHAWBS78AZ88365 1B7HC16Y215771465 1GDJK34K18E210998	Sanitation Sanitation Fleet Maintenance Fleet Maintenance	2005 International/ Leach 2RIII ret 2008 Freightliner/McNeilus refuse 2001 Dodge Ram 1500 2008 Chevrolet 3500 W/Utility Bo	Due for replacement. Damage to front grill area Cab electrical fire Cost of repairs are higher than vehicles value (Totaled in accident
0888 0105	00005223 00003083 00005389 00003082	1HTWGAAR75J152371 2FZHAWBS78AZ88365 1B7HC16Y215771465 1GDJK34K18E210998 1B7HC16Y71S771462	Sanitation Sanitation Fleet Maintenance Fleet Maintenance Fleet Maintenance	2005 International/ Leach 2RIII ref 2008 Freightliner/McNeilus refuse 2001 Dodge Ram 1500 2008 Chevrolet 3500 W/Utility Bo 2001 Dodge 1500	Due for replacement. Damage to front grill area Cab electrical fire Cost of repairs are higher than vehicles value 'Totaled in accident Replaced
0888	00005223 00003083 00005389 00003082 00003758	1HTWGAAR75J152371 2FZHAWBS78AZ88365 1B7HC16Y215771465 1GDJK34K18E210998 1B7HC16Y71S771462 1GTEC14V83Z286687	Sanitation Sanitation Fleet Maintenance Fleet Maintenance Fleet Maintenance Fleet Maintenance	2005 International/ Leach 2RIII ref 2008 Freightliner/McNeilus refuse 2001 Dodge Ram 1500 2008 Chevrolet 3500 W/Utility Bo 2001 Dodge 1500 2003 GMC 1500	Due for replacement. Damage to front grill area Cab electrical fire Cost of repairs are higher than vehicles value 'Totaled in accident Replaced ABS Light is luminated. Cost of repairs exceed vehicles worth
0888 0105	00005223 00003083 00005389 00003082 00003758 n/a	1HTWGAAR75J152371 2FZHAWBS78AZ88365 1B7HC16Y215771465 1GDJK34K18E210998 1B7HC16Y71S771462 1GTEC14V83Z286687 n/a	Sanitation Sanitation Fleet Maintenance Fleet Maintenance Fleet Maintenance Fleet Maintenance Fleet Maintenance Fleet Maintenance	2005 International/ Leach 2RIII rel 2008 Freightliner/McNeilus refuse 2001 Dodge Ram 1500 2008 Chevrolet 3500 W/Utility Bo 2001 Dodge 1500 2003 GMC 1500 2016 Ford explorer Back seats (qt	Due for replacement. Damage to front grill area Cab electrical fire Cost of repairs are higher than vehicles value Totaled in accident Replaced ABS Light is luminated. Cost of repairs exceed vehicles worth Replaced
0888 0105	00005223 00003083 00005389 00003082 00003758	1HTWGAAR75J152371 2FZHAWBS78AZ88365 1B7HC16Y215771465 1GDJK34K18E210998 1B7HC16Y71S771462 1GTEC14V83Z286687	Sanitation Sanitation Fleet Maintenance Fleet Maintenance Fleet Maintenance Fleet Maintenance	2005 International/ Leach 2RIII ref 2008 Freightliner/McNeilus refuse 2001 Dodge Ram 1500 2008 Chevrolet 3500 W/Utility Bo 2001 Dodge 1500 2003 GMC 1500	Due for replacement. Damage to front grill area Cab electrical fire Cost of repairs are higher than vehicles value 'Totaled in accident Replaced ABS Light is luminated. Cost of repairs exceed vehicles worth
0888 0105 0357	00005223 00003083 00005389 00003082 00003758 n/a n/a	1HTWGAAR75J152371 2FZHAWBS78AZ88365 1B7HC16Y215771465 1GDJK34K18E210998 1B7HC16Y715771462 1GTEC14V83Z286687 n/a n/a	Sanitation Sanitation Fleet Maintenance Fleet Maintenance Fleet Maintenance Fleet Maintenance Fleet Maintenance Fleet Maintenance	2005 International/ Leach 2RIII rel 2008 Freightliner/McNeilus refuse 2001 Dodge Ram 1500 2008 Chevrolet 3500 W/Utility Bo 2001 Dodge 1500 2003 GMC 1500 2016 Ford explorer Back seats (qt Folding tables (qty.2)	Due for replacement. Damage to front grill area Cab electrical fire Cost of repairs are higher than vehicles value (Totaled in accident Replaced ABS Light is luminated. Cost of repairs exceed vehicles worth Replaced Replaced Replaced
0888 0105	00005223 00003083 00005389 00003082 00003758 n/a	1HTWGAAR75J152371 2FZHAWBS78AZ88365 1B7HC16Y215771465 1GDJK34K18E210998 1B7HC16Y71S771462 1GTEC14V83Z286687 n/a	Sanitation Sanitation Fleet Maintenance Fleet Maintenance Fleet Maintenance Fleet Maintenance Fleet Maintenance Fleet Maintenance	2005 International/ Leach 2RIII rel 2008 Freightliner/McNeilus refuse 2001 Dodge Ram 1500 2008 Chevrolet 3500 W/Utility Bo 2001 Dodge 1500 2003 GMC 1500 2016 Ford explorer Back seats (qt	Due for replacement. Damage to front grill area Cab electrical fire Cost of repairs are higher than vehicles value Totaled in accident Replaced ABS Light is luminated. Cost of repairs exceed vehicles worth Replaced
0888 0105 0357	00005223 00003083 00005389 00003082 00003758 n/a n/a 00002567	1HTWGAAR75J152371 2FZHAWBS78AZ88365 1B7HC16Y215771465 1GDJK34K18E210998 1B7HC16Y715771462 1GTEC14V83Z286687 n/a n/a 1FAFP52U9WA219213	Sanitation Sanitation Fleet Maintenance Operations	2005 International/ Leach 2RIII rel 2008 Freightliner/McNeilus refuse 2001 Dodge Ram 1500 2008 Chevrolet 3500 W/Utility Bo 2001 Dodge 1500 2003 GMC 1500 2016 Ford explorer Back seats (qt Folding tables (qty.2)	Due for replacement. Damage to front grill area Cab electrical fire Cost of repairs are higher than vehicles value Totaled in accident Replaced ABS Light is luminated. Cost of repairs exceed vehicles worth Replaced Replaced Meets replacement criteria
0888 0105 0357	00005223 00003083 00005389 00003082 00003758 n/a n/a 00002567	1HTWGAAR75J152371 2FZHAWBS78AZ88365 1B7HC16Y215771465 1GDJK34K18E210998 1B7HC16Y715771462 1GTEC14V83Z286687 n/a n/a 1FAFP52U9WA219213	Sanitation Sanitation Fleet Maintenance Building Maintenance	2005 International/ Leach 2RIII rel 2008 Freightliner/McNeilus refuse 2001 Dodge Ram 1500 2008 Chevrolet 3500 W/Utility Bo 2001 Dodge 1500 2003 GMC 1500 2016 Ford explorer Back seats (qt Folding tables (qty.2) 1998 Ford Taurus Frigidaire A/C window unit	Due for replacement. Damage to front grill area Cab electrical fire Cost of repairs are higher than vehicles value (Totaled in accident Replaced ABS Light is luminated. Cost of repairs exceed vehicles worth Replaced Replaced Meets replacement criteria Replaced
0888 0105 0357	00005223 00003083 00005389 00003082 00003758 n/a n/a 00002567	1HTWGAAR75J152371 2FZHAWBS78AZ88365 1B7HC16Y215771465 1GDJK34K18E210998 1B7HC16Y715771462 1GTEC14V83Z286687 n/a n/a 1FAFP52U9WA219213	Sanitation Sanitation Fleet Maintenance Operations	2005 International/ Leach 2RIII rel 2008 Freightliner/McNeilus refuse 2001 Dodge Ram 1500 2008 Chevrolet 3500 W/Utility Bo 2001 Dodge 1500 2003 GMC 1500 2016 Ford explorer Back seats (qt Folding tables (qty.2)	Due for replacement. Damage to front grill area Cab electrical fire Cost of repairs are higher than vehicles value Totaled in accident Replaced ABS Light is luminated. Cost of repairs exceed vehicles worth Replaced Replaced Meets replacement criteria
0888 0105 0357	00005223 00003083 00005389 00003082 00003758 n/a n/a 00002567 n/a	1HTWGAAR75J152371 2FZHAWBS78AZ88365 1B7HC16Y215771465 1GDJK34K18E210998 1B7HC16Y71S771462 1GTEC14V83Z286687 n/a n/a 1FAFP52U9WA219213 n/a n/a	Sanitation Sanitation Fleet Maintenance Operations Building Maintenance Building Maintenance	2005 International/ Leach 2RIII rel 2008 Freightliner/McNeilus refuse 2001 Dodge Ram 1500 2008 Chevrolet 3500 W/Utility Bo 2001 Dodge 1500 2001 Dodge 1500 2003 GMC 1500 2016 Ford explorer Back seats (qt Folding tables (qty.2) 1998 Ford Taurus Frigidaire A/C window unit Whirlpool A/C window unit	Due for replacement. Damage to front grill area Cab electrical fire Cost of repairs are higher than vehicles value Totaled in accident Replaced ABS Light is luminated. Cost of repairs exceed vehicles worth Replaced Replaced Meets replacement criteria Replaced Replaced Replaced Replaced
0888 0105 0357 9813	00005223 00003083 00005389 00003082 00003758 n/a 00002567 n/a n/a 00000730	1HTWGAAR75J152371 2FZHAWBS78AZ88365 1B7HC16Y215771465 1GDJK34K18E210998 1B7HC16Y715771462 1GTEC14V83Z286687 n/a n/a 1FAFP52U9WA219213 n/a n/a 16JF01427F1015930	Sanitation Sanitation Fleet Maintenance Operations Building Maintenance Building Maintenance Parks Dept.	2005 International/ Leach 2RIII rel 2008 Freightliner/McNeilus refuse 2001 Dodge Ram 1500 2008 Chevrolet 3500 W/Utility Bo 2001 Dodge 1500 2003 GMC 1500 2016 Ford explorer Back seats (qt Folding tables (qty.2) 1998 Ford Taurus Frigidaire A/C window unit Whirlpool A/C window unit 1985 Belshe trailer	Due for replacement. Damage to front grill area Cab electrical fire Cost of repairs are higher than vehicles value Totaled in accident Replaced ABS Light is luminated. Cost of repairs exceed vehicles worth Replaced Replaced Meets replacement criteria Replaced Replaced Replaced Needs welding work
0888 0105 0357	00005223 00003083 00005389 00003082 00003758 n/a n/a 00002567 n/a n/a 00000730 00000730 00003433	1HTWGAAR75J152371 2FZHAWBS78AZ88365 1B7HC16Y215771465 1GDJK34K18E210998 1B7HC16Y71S771462 1GTEC14V83Z286687 n/a n/a 1FAFP52U9WA219213 n/a n/a 16JF01427F1015930 70523 1689	Sanitation Sanitation Fleet Maintenance Building Maintenance Building Maintenance Parks Dept. Parks Dept.	2005 International/ Leach 2RIII ref 2008 Freightliner/McNeilus refuse 2001 Dodge Ram 1500 2008 Chevrolet 3500 W/Utility Bo 2001 Dodge 1500 2003 GMC 1500 2016 Ford explorer Back seats (qt Folding tables (qty.2) 1998 Ford Taurus Frigidaire A/C window unit Whirlpool A/C window unit 1985 Belshe trailer 2001 Jacobsen Mower	Due for replacement. Damage to front grill area Cab electrical fire Cost of repairs are higher than vehicles value 'Totaled in accident Replaced ABS Light is luminated. Cost of repairs exceed vehicles worth Replaced Replaced Meets replacement criteria Replaced Replaced Needs welding work Does not run, parts have been removed.
0888 0105 0357 9813	00005223 00003083 00005389 00003082 00003758 n/a 00002567 n/a n/a 00000730	1HTWGAAR75J152371 2FZHAWBS78AZ88365 1B7HC16Y215771465 1GDJK34K18E210998 1B7HC16Y715771462 1GTEC14V83Z286687 n/a n/a 1FAFP52U9WA219213 n/a n/a 16JF01427F1015930	Sanitation Sanitation Fleet Maintenance Operations Building Maintenance Building Maintenance Parks Dept.	2005 International/ Leach 2RIII rel 2008 Freightliner/McNeilus refuse 2001 Dodge Ram 1500 2008 Chevrolet 3500 W/Utility Bo 2001 Dodge 1500 2003 GMC 1500 2016 Ford explorer Back seats (qt Folding tables (qty.2) 1998 Ford Taurus Frigidaire A/C window unit Whirlpool A/C window unit 1985 Belshe trailer	Due for replacement. Damage to front grill area Cab electrical fire Cost of repairs are higher than vehicles value Totaled in accident Replaced ABS Light is luminated. Cost of repairs exceed vehicles worth Replaced Replaced Meets replacement criteria Replaced Replaced Replaced Needs welding work
0888 0105 0357 9813	00005223 00003083 00005389 00003082 00003758 n/a n/a 00002567 n/a n/a 00000730 00003433 n/a	1HTWGAAR75J152371 2FZHAWBS78AZ88365 1B7HC16Y215771465 1GDJK34K18E210998 1B7HC16Y715771462 1GTEC14V83Z286687 n/a n/a 1FAFP52U9WA219213 n/a n/a 16JF01427F1015930 70523 1689 n/a	Sanitation Sanitation Fleet Maintenance Operations Building Maintenance Building Maintenance Parks Dept. Parks Dept. Parks Dept.	2005 International/ Leach 2RIII rel 2008 Freightliner/McNeilus refuse 2001 Dodge Ram 1500 2008 Chevrolet 3500 W/Utility Bo 2001 Dodge 1500 2003 GMC 1500 2016 Ford explorer Back seats (qt Folding tables (qty.2) 1998 Ford Taurus Frigidaire A/C window unit Whirlpool A/C window unit 1985 Belshe trailer 2001 Jacobsen Mower 4 Drawer tan file cabinet	Due for replacement. Damage to front grill area Cab electrical fire Cost of repairs are higher than vehicles value Totaled in accident Replaced ABS Light is luminated. Cost of repairs exceed vehicles worth Replaced Replaced Meets replacement criteria Replaced
0888 0105 0357 9813	00005223 00003083 00005389 00003082 00003758 n/a n/a 00002567 n/a n/a 00000730 00003433 n/a n/a	1HTWGAAR75J152371 2FZHAWBS78AZ88365 1B7HC16Y215771465 1GDJK34K18E210998 1B7HC16Y715771462 1GTEC14V83Z286687 n/a n/a 1FAFP52U9WA219213 n/a n/a 16JF01427F1015930 70523 1689 n/a n/a	Sanitation Sanitation Fleet Maintenance Building Maintenance Building Maintenance Parks Dept. Parks Dept. Parks Dept. Information Technology	2005 International/ Leach 2RIII ref 2008 Freightliner/McNeilus refuse 2001 Dodge Ram 1500 2008 Chevrolet 3500 W/Utility Bo 2001 Dodge 1500 2003 GMC 1500 2016 Ford explorer Back seats (qt Folding tables (qty.2) 1998 Ford Taurus Frigidaire A/C window unit Whirlpool A/C window unit 1985 Belshe trailer 2001 Jacobsen Mower 4 Drawer tan file cabinet Dell 780 PC (qty. 40)	Due for replacement. Damage to front grill area Cab electrical fire Cost of repairs are higher than vehicles value 'Totaled in accident Replaced ABS Light is luminated. Cost of repairs exceed vehicles worth Replaced Replaced Meets replacement criteria Replaced Replaced Needs welding work Does not run, parts have been removed. Replaced Obsolete
0888 0105 0357 9813	00005223 00003083 00005389 00003082 00003758 n/a n/a 00002567 n/a n/a 00000730 00003433 n/a n/a	1HTWGAAR75J152371 2FZHAWBS78AZ88365 1B7HC16Y215771465 1GDJK34K18E210998 1B7HC16Y71S771462 1GTEC14V83Z286687 n/a n/a 1FAFP52U9WA219213 n/a n/a 16JF01427F1015930 70523 1689 n/a n/a	Sanitation Sanitation Fleet Maintenance Building Maintenance Building Maintenance Parks Dept. Parks Dept. Parks Dept. Information Technology Information Technology	2005 International/ Leach 2RIII ref 2008 Freightliner/McNeilus refuse 2001 Dodge Ram 1500 2008 Chevrolet 3500 W/Utility Bo 2001 Dodge 1500 2003 GMC 1500 2016 Ford explorer Back seats (qt Folding tables (qty.2) 1998 Ford Taurus Frigidaire A/C window unit Whirlpool A/C window unit 1985 Belshe trailer 2001 Jacobsen Mower 4 Drawer tan file cabinet Dell 780 PC (qty. 40) Dell 755 PC (qty. 9)	Due for replacement. Damage to front grill area Cab electrical fire Cost of repairs are higher than vehicles value Totaled in accident Replaced ABS Light is luminated. Cost of repairs exceed vehicles worth Replaced Replaced Meets replacement criteria Replaced Replaced Needs welding work Does not run, parts have been removed. Replaced Obsolete Obsolete
0888 0105 0357 9813	00005223 00003083 00005389 00003082 00003758 n/a n/a 00002567 n/a n/a 00000730 00003433 n/a n/a	1HTWGAAR75J152371 2FZHAWBS78AZ88365 1B7HC16Y215771465 1GDJK34K18E210998 1B7HC16Y715771462 1GTEC14V83Z286687 n/a n/a 1FAFP52U9WA219213 n/a n/a 16JF01427F1015930 70523 1689 n/a n/a	Sanitation Sanitation Fleet Maintenance Building Maintenance Building Maintenance Parks Dept. Parks Dept. Parks Dept. Information Technology	2005 International/ Leach 2RIII ref 2008 Freightliner/McNeilus refuse 2001 Dodge Ram 1500 2008 Chevrolet 3500 W/Utility Bo 2001 Dodge 1500 2003 GMC 1500 2016 Ford explorer Back seats (qt Folding tables (qty.2) 1998 Ford Taurus Frigidaire A/C window unit Whirlpool A/C window unit 1985 Belshe trailer 2001 Jacobsen Mower 4 Drawer tan file cabinet Dell 780 PC (qty. 40)	Due for replacement. Damage to front grill area Cab electrical fire Cost of repairs are higher than vehicles value 'Totaled in accident Replaced ABS Light is luminated. Cost of repairs exceed vehicles worth Replaced Replaced Meets replacement criteria Replaced Replaced Needs welding work Does not run, parts have been removed. Replaced Obsolete
0888 0105 0357 9813	00005223 00003083 00005389 00003082 00003758 n/a n/a 00002567 n/a n/a 00000730 00003433 n/a n/a n/a	1HTWGAAR75J152371 2FZHAWBS78AZ88365 1B7HC16Y215771465 1GDJK34K18E210998 1B7HC16Y71S771462 1GTEC14V83Z286687 n/a n/a 1FAFP52U9WA219213 n/a n/a 16JF01427F1015930 70523 1689 n/a n/a n/a	Sanitation Sanitation Fleet Maintenance Operations Building Maintenance Building Maintenance Parks Dept. Parks Dept. Parks Dept. Information Technology Information Technology Information Technology Information Technology	2005 International/ Leach 2RIII ref 2008 Freightliner/McNeilus refuse 2001 Dodge Ram 1500 2008 Chevrolet 3500 W/Utility Bo 2001 Dodge 1500 2016 Ford explorer Back seats (qt Folding tables (qty.2) 1998 Ford Taurus Frigidaire A/C window unit Whirlpool A/C window unit 1985 Belshe trailer 2001 Jacobsen Mower 4 Drawer tan file cabinet Dell 780 PC (qty. 40) Dell 755 PC (qty. 9) Dell GK620 PC (qty. 3) Dell 380PC	Due for replacement. Damage to front grill area Cab electrical fire Cost of repairs are higher than vehicles value Totaled in accident Replaced ABS Light is luminated. Cost of repairs exceed vehicles worth Replaced Replaced Meets replacement criteria Replaced Replaced Needs welding work Does not run, parts have been removed. Replaced Obsolete Obsolete
0888 0105 0357 9813	00005223 00003083 00005389 00003082 00003758 n/a 00002567 n/a n/a 00000730 00003433 n/a n/a n/a n/a n/a	1HTWGAAR75J152371 2FZHAWBS78AZ88365 1B7HC16Y215771465 1GDJK34K18E210998 1B7HC16Y715771462 1GTEC14V83Z286687 n/a n/a 1FAFP52U9WA219213 n/a n/a 16JF01427F1015930 70523 1689 n/a n/a n/a n/a n/a	Sanitation Sanitation Fleet Maintenance Operations Building Maintenance Building Maintenance Parks Dept. Parks Dept. Parks Dept. Information Technology Information Technology Information Technology Information Technology Information Technology Information Technology	2005 International/ Leach 2RIII rel 2008 Freightliner/McNeilus refuse 2001 Dodge Ram 1500 2008 Chevrolet 3500 W/Utility Bo 2001 Dodge 1500 2001 Endoge 1500 2001 Grote explorer Back seats (qt Folding tables (qty.2) 1998 Ford Taurus Frigidaire A/C window unit Whirlpool A/C window unit 1985 Belshe trailer 2001 Jacobsen Mower 4 Drawer tan file cabinet Dell 780 PC (qty. 40) Dell 755 PC (qty. 9) Dell GX620 PC (qty. 3)	Due for replacement. Damage to front grill area Cab electrical fire Cost of repairs are higher than vehicles value 'Totaled in accident Replaced ABS Light is luminated. Cost of repairs exceed vehicles worth Replaced Replaced Meets replacement criteria Replaced Replaced Needs welding work Does not run, parts have been removed. Replaced Obsolete Obsolete Obsolete Obsolete
0888 0105 0357 9813	00005223 00003083 00005389 00003082 00003758 n/a n/a 00002567 n/a n/a 00000730 00003433 n/a n/a n/a n/a n/a n/a	1HTWGAAR75J152371 2FZHAWBS78AZ88365 1B7HC16Y215771465 1GDJK34K18E210998 1B7HC16Y71S771462 1GTEC14V83Z286687 n/a n/a 1FAFP52U9WA219213 n/a n/a 16JF01427F1015930 70523 1689 n/a	Sanitation Sanitation Fleet Maintenance Operations Building Maintenance Building Maintenance Parks Dept. Parks Dept. Parks Dept. Information Technology	2005 International/ Leach 2RIII ref 2008 Freightliner/McNeilus refuse 2001 Dodge Ram 1500 2008 Chevrolet 3500 W/Utility Bo 2001 Dodge 1500 2003 GMC 1500 2016 Ford explorer Back seats (qt Folding tables (qty.2) 1998 Ford Taurus Frigidaire A/C window unit Whirlpool A/C window unit Whirlpool A/C window unit 1985 Belshe trailer 2001 Jacobsen Mower 4 Drawer tan file cabinet Dell 780 PC (qty. 40) Dell 755 PC (qty. 9) Dell GX620 PC (qty. 3) Dell 380PC Dell 760 PC (qty. 2)	Due for replacement. Damage to front grill area Cab electrical fire Cost of repairs are higher than vehicles value 'Totaled in accident Replaced ABS Light is luminated. Cost of repairs exceed vehicles worth Replaced Replaced Meets replacement criteria Replaced Replaced Needs welding work Does not run, parts have been removed. Replaced Obsolete Obsolete Obsolete Obsolete Obsolete Obsolete

SURPLUS VEHICLES AND EQUIPMENT CONTINUED

UNIT#	ASSET #	VIN#	DEPARTMENT	DESCRIPTION	REASON FOR DISPOSAL
	5759	n/a	Information Technology	White box PC (qty.2)	Obsolete
	n/a	n/a	Information Technology	Black box PC	Obsolete
	n/a	n/a	Information Technology	Dell 1720 printer	Obsolete
	n/a	n/a	Information Technology	Dell 1720N printer (qty.3)	Obsolete
	n/a	n/a	Information Technology	Dell 1710 printer (qty.3)	Obsolete
	n/a	n/a	Information Technology	Dell 1320C printer	Obsolete
	n/a	n/a	Information Technology	HP 1300 printer	Obsolete
	n/a	n/a	Information Technology	HP 1300N printer	Obsolete
	n/a	n/a	Information Technology	Dell 2330DN printer	Obsolete
	n/a	n/a	Information Technology	Dell 3000CN printer	Obsolete
	00006317	n/a	Information Technology	HP laserjet 4050	Obsolete
	00006191	n/a	Information Technology	HP laserjet 4050	Obsolete
	00006201	n/a	Information Technology	HP laserjet 4050	Obsolete
	n/a	n/a	Information Technology	HP psc 1350	Obsolete
	n/a	n/a	Information Technology	HP officejet K8600 printer	Obsolete
	n/a	n/a	Information Technology	HP laserjet CP5225 printer	Obsolete
	n/a	n/a	Information Technology	HP deskjet 1220C printer	Obsolete
	n/a	n/a	Information Technology	HP deskjet 960C printer	Obsolete
	00006326	n/a	Information Technology	HP designjet 500PS plotter	Obsolete
	n/a	n/a	Information Technology	HP Procurve 2312 (qty.3)	Obsolete
	n/a	n/a	Information Technology	Brothers intellifax 775	Obsolete
	n/a	n/a	Information Technology	Buffalo air station (qty.2)	Obsolete
	n/a	n/a	Information Technology	Dell axim x5pda	Obsolete
	n/a	n/a	Information Technology	Dell axim x5 docking station	Obsolete
	n/a	n/a	Information Technology	Dell monitor (qty.2)	Obsolete
	n/a	n/a	Information Technology	Dell D600 laptop	Obsolete
	n/a	n/a	Information Technology	Benq FP767 monitor	Obsolete
	n/a	n/a	Information Technology	Philips 107e6 monitor	Obsolete
	n/a	n/a	Information Technology	Dell 1907fpt monitor	Obsolete
	n/a	n/a	Information Technology	Dell 1704fptt monitor(qty.2)	Obsolete
	n/a	n/a	Information Technology	Dell 1908fpt monitor	Obsolete
	n/a	n/a	Information Technology	Dell E172fpb monitor	Obsolete
	n/a	n/a	Information Technology	Verifone omni 3200 credit card ma	Obsolete
	n/a	n/a	Information Technology	Dell W5001C HD TV (qty.2)	Obsolete
	n/a	n/a	Information Technology	EV SX 80 Monitor(qty4)	Obsolete
	n/a	n/a	Information Technology	EV S-40 Monitor(qty.2)	Obsolete
	00008661	n/a	Information Technology	Rushworks video server	Obsolete
	n/a	n/a	Information Technology	Avitech Rainer Video input (qty.2)	Obsolete
	n/a	n/a	Information Technology	Roland V-8 Video mixer	Obsolete
	n/a	n/a	Information Technology	Jotto Desk dual pass thru dock	Obsolete
	n/a	n/a	Information Technology	Dell desktop docking station	Obsolete
	n/a	n/a	Information Technology	Martin yale paper binder	Obsolete
	n/a	n/a	Information Technology	Atus CP8506 power supply (qty.3)	
	n/a	n/a	Information Technology	Electro-voice CPS1 speaker input	
	n/a	n/a	Information Technology	Superlux PS-2 phantom power sup	
	n/a	n/a	Information Technology	Lithonia lighting board	Obsolete
	00006137	n/a	Information Technology	Fujitsu M4097D scanner	Obsolete
	n/a	n/a	Information Technology		Obsolete
	n/a	n/a	Information Technology	Four port video splitter	Obsolete
	n/a	n/a	Information Technology	Linksys etherfast 4124 switch	Obsolete
	n/a	n/a	Information Technology	Logitech attack 3 joystick	Obsolete
	n/a	n/a	Information Technology	Epson EMP-7600 projector	Obsolete
	n/a	n/a	Information Technology	Black wall mountable rack enclosu	
	n/a	n/a	Information Technology	Exetron SA series amplifier	Obsolete
	n/a	n/a	Information Technology	Nady 401X quad receiver	Obsolete
	n/a	n/a	Information Technology	Furman PS pro amplifier	Obsolete
	n/a	n/a	Information Technology	Furman Q-301b graphic equalizer	
	n/a	n/a	Information Technology	Furman SM-3B stero mixer	Obsolete
	n/a	n/a	Information Technology	Protech audio microphone device	Obsolete