

PROJECT REPORT

DATE:	04/16/24
NAME	Patrick Wilson, PE, CFM, Stormwater Division Manager, City of Broken Arrow
ADDRESS / LOCATION	12300 E 91 st St Broken Arrow, OK 74012
WATERSHED	Haikey
ESTIMATE	\$50,000.00 for design
CASE NO.	24-002

DESCRIPTION

The four-cell box culvert under Washington Ave (91st) near the Diocese of Tulsa in Broken Arrow was widened during the roadway widening project. The construction/widening of the boxes was completed, but the armoring did not take place. The armoring project was bid out by the City in 2021, but did not receive any bids.

The culvert has silted in and blocking flow in 3 of the boxes. This appears to be causing the flow through the one box to increase thereby increasing the normal velocity through the one cell.

The increased velocity has caused the south bank of Haikey creek to erode. The project will be to clean the box culvert, the north channel, and to armor the southern bank.

The area is located in a floodplain and a blue line stream.

Staff is requesting \$50,000.00 in design funds for erosion control and channel stabilization

BENEFIT

To clean out the channel under Washington St and keep Haikey creek flowing unimpeded leading to the proper floodplain and to mitigate erosion.

RECOMMENDATION

Approve the request for the expenditure of \$50,000 to design erosion control and channel stabilization of the southern bank.

COMPLETED BY: Nathanael Kohl

DATE: 04/16/24

City of Broken Arrow

Drainage Advisory Committee



APPLICATION

DATE:	
OWNER NAME:	
PHONE NUMBER:	
EMAIL ADDRESS:	
OWNER MAILING ADDRESS:	
ADDRESS OF PROPERTY WITH DRAINAGE PROBLEM:	
LOCATION OF DRAINAGE ISSUE ON PROPERTY:	


DESCRIPTION OF PROBLEM: (*PHOTOS SHOULD ACCOMPANY APPLICATION)

--	--

Signature: [Stormwater Engineering Division](#)

RETURN TO STORMWATER DIVISION MANAGER'S OFFICE, PO BOX 610 Broken Arrow, OK 74013

Stormwater Utility Map




4/8/2024, 9:40:17 AM

- Sections (PLSS)
- YES
- Blue Line Streams (ODOT)
- Stormwater Lines
- Dentention Ponds
- NO
- Private
- Stormwater Structures (Private)
- Broken Arrow
- State-Federal
- Inlet
- Inlet
- Manhole
- Other


- Inlet
- Inlet
- Manhole
- Other
- ▲ Other
- ▲ Other
- ▲ Other
- ▲ Other
- Inlet
- Inlet
- Inlet
- Inlet

1:22,031



Copyright nearmap 2015. Source: Esri, Maxar, Earthstar Geographics, and the GIS User Community. Sources: Esri, TomTom, Garmin, FAO, NOAA, USGS, © OpenStreetMap contributors, and the GIS User Community

Stormwater Utility Map



4/8/2024, 9:31:04 AM

1:688

0 0 0.01 0.01 0.01 0.02 mi
0 0.01 0.01 0.01 0.01 0.03 km

Parcels

Stormwater Lines

Contours_2ft

Sections (PLSS)

Broken Arrow

2ft

Blue Line Streams (ODOT)

Stormwater Structures


10ft

Inlet

Copyright nearmap 2015. Source: Esri, Maxar, Earthstar Geographics, and the GIS User Community. Sources: Esri, TomTom, Garmin, FAO, NOAA, USGS, © OpenStreetMap contributors, and the GIS User Community

City of Broken Arrow

Stormwater Utility Map



4/8/2024, 9:34:40 AM

1:688

0 0 0.01 0.01 0.01 0.02 mi
0 0.01 0.01 0.01 0.01 0.02 km

Parcels	Stormwater Lines	Contours_2ft
Sections (PLSS)	Broken Arrow	2ft
Blue Line Streams (ODOT)	Stormwater Structures	10ft
	Inlet	

Copyright nearmap 2015. Source: Esri, Maxar, Earthstar Geographics, and the GIS User Community. Sources: Esri, TomTom, Garmin, FAO, NOAA, USGS, © OpenStreetMap contributors, and the GIS User Community

City of Broken Arrow



