

Drainage Advisory Committee

PROJECT REPORT

DATE:	01/14/2025
NAME	Sarah Walters, PE, CFM, Stormwater Project Manager, City of Broken Arrow
ADDRESS / LOCATION	12300 E 91 st St Broken Arrow, OK 74012
WATERSHED	Haikey
ESTIMATE	\$430,000.00 for construction
CASE NO.	24-002

DESCRIPTION

The four-cell box culvert under Washington Ave (91st) near the Diocese of Tulsa in Broken Arrow was widened during the roadway widening project. The construction/widening of the boxes was completed, but the armoring did not take place. The armoring project was bid out by the City in 2021, but did not receive any bids.

The culvert has silted in and is blocking flow in 3 of the boxes. This appears to be causing the flow through the one box to increase thereby increasing the normal velocity through the one cell.

The increased velocity has caused the south bank of Haikey creek to erode. The project will be to clean the box culvert, the north channel, and to armor the south-east bank.

Money for the design portion of this project was presented and recommended by the DAC on 4/29/24.

The area is located in a floodplain and a blue line stream.

Staff is requesting \$430,000.00 in construction funds for erosion control and channel stabilization.

BENEFIT

To clean out the channel under Washington St and keep Haikey creek flowing unimpeded leading to the proper floodplain and to mitigate erosion.

RECOMMENDATION

Approve the request for the expenditure of \$430,000 to construct erosion control and channel stabilization of the southern bank.

COMPLETED BY: Sarah Walters

DATE: 01/14/25

City of Broken Arrow

BROKEN ARROW Where opportunity lives

Drainage Advisory Committee


APPLICATION

DATE:	
OWNER NAME:	
PHONE NUMBER:	
EMAIL ADDRESS:	
OWNER MAILING ADDRESS:	
ADDRESS OF PROPERTY WITH DRAINAGE PROBLEM:	
LOCATION OF DRAINAGE ISSUE ON PROPERTY:	

DESCRIPTION OF PROBLEM:	(*PHOTOS SHOULD ACCOMPANY APPLICATION)
Signature: Stormwater Engineer	ering Division

RETURN TO STORMWATER DIVISION MANAGER'S OFFICE, PO BOX 610 Broken Arrow, OK 74013

Stormwater Utility Map



4/8/2024, 9:40:17 AM


Sections (PLSS)	YES	Private		Inlet	•	Other ^ Other
Blue Line Streams (ODOT)	Stormwater Lines	Stormwater Structures (Private)		Inlet	•	Other Stormwater Structures
Dentention Ponds	Broken Arrow	Inlet	۲	Manhole	•	Other Inlet
NO	State-Federal	Inlet		Other		Other Inlet

Copyright nearmap 2015, Source: Esri, Maxar, Earthstar Geographics, and the GIS User Community, Sources: Esri, TomTom, Garmin, FAO, NOAA, USGS, © OpenStreetMap contributors, and the GIS User Community

City of Broken Arrow


Copyright nearmap 2015 | Maxar | City of Broken Arrow Geospatial Services Division | City of Broken Arrow | Tulsa County Assessor | Esri Community Maps Contributors, City of Tulsa, Texas Parks & Wildlife, © OpenStreetMap, Microsoft, Esri, TomTom, Garmin, SafeGraph, GeoTechnologies, Inc,

Stormwater Utility Map



4/8/2024, 9:31:04 AM





Copyright nearmap 2015, Source: Esri, Maxar, Earthstar Geographics, and the GIS User Community, Sources: Esri, TomTom, Garmin, FAO, NOAA, USGS, © OpenStreetMap contributors, and the GIS User Community

City of Broken Arrow


Copyright nearmap 2015 | Maxar | City of Broken Arrow Geospatial Services Division | City of Broken Arrow | Tulsa County Assessor | Esri Community Maps Contributors, City of Tulsa, Texas Parks & Wildlife, © OpenStreetMap, Microsoft, Esri, TomTom, Garmin, SafeGraph, GeoTechnologies, Inc,

Stormwater Utility Map



4/8/2024, 9:34:40 AM





Copyright nearmap 2015, Source: Esri, Maxar, Earthstar Geographics, and the GIS User Community, Sources: Esri, TomTom, Garmin, FAO, NOAA, USGS, © OpenStreetMap contributors, and the GIS User Community

City of Broken Arrow

Copyright nearmap 2015 | Maxar | City of Broken Arrow Geospatial Services Division | City of Broken Arrow | Tulsa County Assessor | Esri Community Maps Contributors, City of Tulsa, Texas Parks & Wildlife, © OpenStreetMap, Microsoft, Esri, TomTom, Garmin, SafeGraph, GeoTechnologies, Inc,

