## SUMMIT TRUCK GROUP

Repair Management

1023 N GARNETT RD. - TULSA, OK 74116 Phone: (918) 438-2000 - Fax: (918) 234-6151

Estimate Number: 2346806 - RO Number: TBD

Service Writer: Mitch VanSyckel - Date: 2/7/2019 12:31 PM (C)

Currency: USD

## **Unit No: 1402**

## Broken Arrow, City Of

VIN: 1HTJSSKK1EH498200

Model: TERRASTAR SFA 4x2

Engine: MAXXFORCE 7, 300 HP/2800 RPM GOV SPD

Make: International Delivered: 4/22/2013

In Service: 5 Years 11 Months

Mileage: 0 Eng Hrs: 0

Recall/AFC: No

Contact Name: MATT\_SMITH

Position: service-primary, parts-primary

Phone: (918) 259-8371

E-Mail:

PO Number:

			والمراب والمرابع والمنافق والمنافقة	in the Column to the April of the Column to
Operation Section A	Labor Cost	Parts Cost	Core Charge	Total Cost
Engine Assembly (COMPLETE), Remove & Reinstall	\$2,325.00	\$19,789.48	\$7,200.00	\$29,314.48
(8) FLEETRITE COOLANT; TYPE: NOAT RED EXTENDED LIFE; MIX: 50/50; SIZE: GALLON; COUNTRY: US (1) FILTER, AIR (2) CLAMP, HOSE RADIATOR INLET 2.25"-3.13" INSIDE DIAMETER (2) FLEETRITE POWER STEERING FLUID; SIZE: 32 OZ; TYPE: POWER STEERING FLUID (35) TIES (1) KIT, TANDEM PUMP O-RING (1) RING, "O" (2) GASKET TURBOCHARGER INLET (6) BOLT M10 X 30 HF HIGH TEMPERATURE (1) O-RING (2) GASKET DISTRIBUTION DUCT (22) OIL (1) ENGINE, TRIMMED SVC TERRA V152/179				-
REMOVE AND REINSTALL ALL AMBULANCE EQUIPMENT IN CAB	\$1,596.50	\$0.00	\$0.00	\$1,596.50
Complaint: Not Available				
Cause: Not Available				
Correction: Not Available	- Ithin a samina a s			
Operation Section B	Labor Cost	Parts Cost	Core Charge	Total Posi
Road Test / Test Drive - Fixed Cost	\$0.00	\$0.00	\$0.00	\$72.50

Operation S	Section B	Labor Cost	Parts Cost	Core Charge	i i i i i i i i i i i i i i i i i i i
Road Test /	Test Drive - Fixed Cost	\$0.00	\$0.00	\$0.00	\$72.50
Complaint:	Not Available				
Cause:	Not Available				
Correction:	Not Available				

Operation (Un-Sectioned)	Labor Cost	Parts Cost	Core Charge	Total Cost
Computer Hook Up - Fixed Cost	\$0.00	\$0.00	\$0.00	\$72.00

Notes:

[2/7/2019 12:31 PM] - Dealer: REMOVE AND REINSTALL ENGINE AND

EQUIPMENT IN CÅB. ESTIMATE STATEMENT, PLEASE READ

NOTE 1: PARTS AND LABOR LISTED ABOVE ARE ONLY AN ESTIMATE OF THE REPAIRS WE SEE ARE NEEDED AT THIS POINT. WHEN PARTS ARE REMOVED AND FURTHER INSPECTION IS ALLOWED, IT''S

POSSIBLE THAT AN ADDITIONAL ESTIMATE FOR THOSE REPAIRS MAY Shop: BE REQUIRED AND SUBMITTED TO YOU FOR APPROVAL. FURTHER

Summary

 Parts:
 \$19,789.48

 Core:
 \$7,200.00

 Labor:
 \$3,921.50

\$250.00