Dampf, April

From:	Bell, Debby
Sent:	Tuesday, February 25, 2025 1:15 PM
To:	Dampf, April
Subject:	FW: fire investigation report

On the fire run report that Calvin wanted for 21410 E 38th St and why I could find anything. Per FM Sharp that house is on a curve and sits at both S 214th & E 38th St. the fire run report 2023-15905 of 3745 S 214th St is the correct fire run report you were wanting for 21410 E 38th St. there was also an arson investigation, but nothing could be proved.

Debs

From: Sharp, Justin <jsharp@brokenarrowok.gov>
Sent: Tuesday, February 25, 2025 12:45 PM
To: Bell, Debby <DBell@BrokenArrowOK.Gov>
Subject: RE: fire investigation report

Debby,

Its going to be 3745 South 214th East Avenue. NFIRS 2023-15905.

From: Bell, Debby <DBell@BrokenArrowOK.Gov>
Sent: Tuesday, February 25, 2025 12:40 PM
To: Sharp, Justin <jsharp@brokenarrowok.gov>
Subject: fire investigation report

You were correct the fire was 12/2023
21410 E 38th St
I'm still not able to find a fire run report, but if there is a fire Investigation report should there not be a fire run report?
Debs

Serving Others,

Debra L. Bell
Administrative Assistant
Fire Department

City of Broken Arrow
1101 North 6th Street
Broken Arrow, OK 74012
office: 918-259-8360 **Ext. 6471**
dbell@brokenarrowok.gov | www.brokenarrowok.gov
facebook | twitter | youtube

NFIRS-1 Basic

A

72002	OK	12	17	2023	Station 6 (6)	2023-15905	0
FDID	State	Month	Day	Year	Station	Number	Exposure

B Location Type

Census tract:

☑ Street Address
☐ Intersection
☐ In Front Of
☐ Rear Of
☐ Adjacent To
☐ Directions
☐ US National Grid

3745	S-South	214TH	AVE-Avenue	E-East
Number	Prefix	Street or Highway	Street Type	Suffix

	City of Broken Arrow	OK	74014
Apt./Suite/Room	City	State	Zip Code

Cross Street

C

Incident Type

111-Building fire

D

Aid Given Or Received

☐ 1 Mutual Aid Received
☐ 2 Auto. Aid Received
☐ 3 Mutual Aid Given
☐ 4 Auto. Aid Given
☐ 5 Other Aid Given
☑ None

Their FDID	Their State

Their Incident Number

E1 Dates and Times

Alarm	12	17	2023	06:05	
Arrival	12	17	2023	06:14	
Controlled					
Last Unit Cleared	12	17	2023	18:04	

E2 Shifts and Alarms

B Shift		W27
Shift or Platoon	Alarms	District

E3 Special Studies

ID#	Value

F Actions Taken

11-Extinguishment by fire service personnel

Primary Action Taken

12-Salvage & overhaul

Additional Action Taken

51-Ventilate

Additional Action Taken

G1 Resources

☐ Apparatus or Personnel Module is used.

	Apparatus	Personnel
Suppression	9	10
EMS	4	7
Other	4	6

Resource counts include aid received resources.

G2 Estimated Dollar Losses and Values

Losses: Required for all fires if known. Optional for all non-fires.   None

Property: $ _____   ☑

Contents: $ _____   ☑

Pre-Incident Values: Optional   None

Property: $ _____   ☐

Contents: $ _____   ☐

Completed Modules
☐ 2 - Fire
☐ 3 - Structure Fire
☐ 4 - Civilian Fire Cas.
☐ 5 - Fire Service Cas.
☐ 6 - EMS
☐ 7 - HazMat
☐ 8 - Wildland Fire
☐ 9 - Apparatus
☐ 10 - Personnel
☐ 11 - Arson

H1 Casualties ☐None

	Deaths	Injuries
Fire Service	0	0
Civilian	0	0

H2 Detector
Required for Confined Fires
☐ 1 - Detector Alerted Occupants
☐ 2 - Detector Did Not Alert Them
☐ 3 - Unknown

H3 Hazardous Materials Release
☐ 1 - Natural Gas
☐ 2 - Propane Gas
☐ 3 - Gasoline
☐ 4 - Kerosene
☐ 5 - Diesel Fuel / Fuel Oil
☐ 6 - Household Solvents
☐ 7 - Motor Oil
☐ 8 - Paint
☐ 0 - Other
☐ None

I Mixed Use Property
☐ Not Mixed
☐ 10 - Assembly Use
☐ 20 - Education Use
☐ 33 - Medical Use
☐ 40 - Residential Use
☐ 51 - Row Of Stores
☐ 53 - Enclosed Mall
☐ 58 - Business and
    Residential
☐ 59 - Office Use
☐ 60 - Industrial Use
☐ 63 - Military Use
☐ 65 - Farm Use
☐ 00 - Other Mixed Use

J Property Use ☐None
Structures
131	Church, Place of Worship
161	Restaurant or Cafeteria
162	Bar/Tavern or Nightclub
213	Elementary School, Kindegarten
215	High School, Junior High
241	College, Adult Education
311	Nursing Home
331	Hospital

341	Clinic, Clinic-Type Infirmary
342	Doctor/Dentist Office
361	Prison or Jail, Not Juvenile
419	1- or 2-Family Dwelling
429	MultiFamily Dwelling
439	Rooming/Boarding House
449	Commerical Hotel or Motel
459	Residential, Board and Care
464	Dormitory/Barracks
519	Food and Beverage Sales

539	Household Goods, Sales, Repairs
571	Gas or Service Station
579	Motor Vehicle/Boat Sales/Repairs
599	Business Office
615	Electric-Generating Plant
629	Laboratory/Science Laboratory
700	Manufacturing Plant
819	Livestock/Poultry Storage (Barn)
882	Non-Residential Parking Garage
891	Warehouse

Outside
124	Playground or Park
655	Crops or Orchard
669	Forest (Timberland)
807	Outdoor Storage Area
919	Dump or Sanitary Landfill
931	Open Land or Field
936	Vacant Lot

938	Graded/Cared for Plot of Land
946	Lake, River, Stream
951	Railroad Right-of-Way
960	Other Street
961	Highway/Divided Highway
962	Residential Street/Driveway
981	Construction Site
984	Industrial Plant Yard

Property Use:

_____

Description

Look up and enter a Property Use code and description only if you have NOT checked a Property Use box.

K2

Owner

Local Option	Person/Entity Type	Business Name (if applicable)	Phone Number

Mr., Ms., Mrs.	First Name	MI	Last Name	Suffix

Number	Prefix	Street or Highway	Street Type	Suffix

Post Office Box	Apt./Suite/Room	City

State	Zip Code

L Remarks:

All units dispatched and responded emergency status to a reported structure fire at the above address. Initial reports given to dispatch by bystanders stated they believed children lived in the house. They stated that there were no cars in the driveway and no one was standing outside of the residence. Reports also stated that the fire in the initial structure was starting to spread to an adjacent structure as well.

L6 arrived on scene first and gave an onscene and 360 report. L6 decided to employee a defensive strategy and began pulling defensive lines off L6.

R1 arrived on scene 2nd and went all in for VEIS of the survivable space of the exposure that was beginning to catch fire.

E4 arrived next on scene and established command.

Shortly after E4 arrived on scene, FD211 arrived and assumed command and asked for the incident commander to report to the command vehicle. E4 arrived at the command post and gave a report. E4 was then assigned exterior division with Sqd6 working for them. Their boundaries were the initial structure that was on fire. Their objective was fire extinguishment.

E1 was then assigned interior division of the exposure with L6 and Sqd4 working for them. After working for a short time Interior division stated that did not need Sqd4 working interior. Command then reassigned Sqd4 to the Exterior Division.

FD212 was assigned Medical Group Supervisor with Sqd1 working for them. Sqd1 was instructed to bring their cot to the command post and report to Med...

Full primary narrative can be found in NFIRS 1S - Supplemental

---

M Authorization

101651	PHILLIPS, BRANSON	CPT	BC	12/19/2023
Officer In Charge ID	Signature	Position or Rank	Assignment	Date
100171	BOECKMAN, JILL	LT	CPT	12/17/2023
Member Making Report ID	Signature	Position or Rank	Assignment	Date

NFIRS-2 Fire

A

72(02	OK	12	17	2023	Station 6 (6)	2023-15905	0
FDII	State	Month	Day	Year	Station	Number	Exposure

B

Property Details

B1 | 1 | .. Not Residential

Estimated number of residential living units in the building of origin whether or not all units became involved

B2 | 1 | . Buildings Not Involved

Number of buildings involved

B3 | | : None . Less than 1 acre

Acres burned (outside fires)

C

On-Site Materials Or Products

On-Site Materials Storage Use

D

Ignition

D1 | Undetermined |

Area of Fire Origin

D2 | Undetermined |

Heat Source

D3 | Undetermined |

Item First Ignited

D4

Type of Material First Ignited

E1

Cause of Ignition

. 1 - Intentional
. . 2 - Unintentional
... 3 - Failure of Equipment or Heat Source
. 4 - Act of Nature
: 5 - Cause Under Investigation
_ U - Cause Undetermined After Investigation

E2

Factors Contributing to Ignition

| Undetermined |

Factor Contributing to Ignition

E3

Human Factors Contributing to Ignition

Check all applicable boxes
: None
. 1 - Asleep
. 2 - Possibly impaired by alcohol or drugs
_ 3 - Unattended person
_ 4 - Possibly Mentally Disabled
_ 5 - Physically Disabled
_ 6 - Multiple Persons Involved

_ 7 - Age Was A Factor

Estimated Age of Person Involved | |

. Male : Female

F1

Equipment Involved In Ignition

⊔

Equipment Involved

Bran J | |
Mod :l | |
Seria! # | |
Year | |

F2

Equipment Power Source

⊔

Equipment Power Source

F3

Equipment Portability

. . 1 - Portable
.. 2 - Stationary
Portable equipment normally can be moved by one or two persons.

G

Fire Suppression Factors

H1

Mobile Property Involved

_ 1 - Not involved in ignition, but burned
_ 2 - Involved in ignition, but did not burn
... 3 - Involved in ignition and burned
  None

Mobile Property Model

State   License Plate Number

H2

Mobile Property Type and Make

Ⅱ

Mobile Property Type

Mobile Property Make

Year

VIN

Local Use

‾ Pre-Fire Plan Available
_ Arson Report Attached
  Police Report Attached
_ Coroner Report Attached
  Other Reports Attached

NFIRS-3 Structure Fire

I1 Structure Type	I2 Building Status	I3 Building Height	I4 Main Floor Size
... 1 - Enclosed Building _.. 2 - Portable/Mobile Structure ...: 3 - Open Structure 4 - Air-Supported Structure 5 - Tent 6 - Open Platform 7 - Underground Structure 8 - Connective Structure 0 - Other	1 - Under Construction .2 - In Normal Use .3 - Idle, Not Routinely Used 4 - Under Major Renovation 5 - Vacant and Secured 6 - Vacant and Unsecured 7 - Being Demolished 0 - Other U - Undetermined	[1] Number of Stories At/Above Grade [0] Number of Stories Below Grade	[1900] Total Square Feet **OR** ⌊⌋ BY ⌊⌋ Length (ft) X Width (ft)

J1
Fire Origin

[1   ]   Below Grade

Story of Fire Origin

J2
Fire Spread

. Confined to Object of Origin
_ 2 - Confined to Room of Origin
3 - Confined to Floor of Origin
4 - Confined to Building of Origin
5 - Beyond Building of Origin

J3
Number of Stories Damaged By Flame

⌊____⌋ Number of Stories w/Minor Damage (1-24%)
⌊____⌋ Number of Stories w/Significant Damage (25-49%)
⌊____⌋ Number of Stories w/Heavy Damage (50-74%)
⌊____⌋ Number of Stories w/Extreme Damage (75-100%)

*Count the roof as part of the highest story

K
Type of Material Contributing Most to Flame Spread

K1 ⌊⌋

Item Contributing Most
to Flame Spread

K2 ⌊⌋

Type of Material Contributing
Most To Flame Spread

L1
Presence of Detectors

_ N - None Present
1 - Present
U - Undetermined

L2
Detector Type

1 - Smoke
_ 2 - Heat
3 - Combination of Smoke and Heat
.. 4 - Sprinkler, Water Flow Detection
5 - More Than One Type Present
... 0 - Other
U - Undetermined

L3
Detector Power Supply

. 1 - Battery Only
2 - Hardwire Only
3 - Plug-In
4 - Hardwire With Battery
_ 5 - Plug-In With Battery
6 - Mechanical
7 - Multiple Detectors
& Power Supplies
0 - Other
.. U - Undetermined

L4
Detector Operation

_ 1 - Fire Too Small To
Activate
2 - Operated
3 - Failed To Operate
U - Undetermined

L5
Detector Effectiveness

_ 1 - Alerted Occupants, Occupants Responded
2 - Alerted Occupants, Occupants Failed to Respond
3 - There Were No Occupants
4 - Failed to Alert Occupants
... U - Undetermined

L6
Detector Failure Reason

_ 1 - Power Failure, Shutoff, or Disconnect
2 - Improper Installation or Placement
_ 3 - Defective
4 - Lack of Maintenance, Dirty
_ 5 - Battery Missing or Disconnected
6 - Battery Discharged or Dead
_ 0 - Other
U - Undetermined

M1

Presence of Automatic Extinguishing System

- N - None Present
- 1 - Present
- 2 - Partial System Present
- U - Undetermined

M2

Type of Automatic Extinguishing System

- 1 - Wet-Pipe Sprinkler
- 2 - Dry-Pipe Sprinkler
- 3 - Other Sprinkler System
- 4 - Dry Chemical System
- 5 - Foam System
- 6 - Halogen-Type System
- 7 - Carbon Dioxide System
- 0 - Other
- U - Undetermined

Required if fire was within designed range of AES

M3

Operation of Automatic Extinguishing System

- 1 - Operated/Effective
- 2 - Operated/Not Effective
- 3 - Fire Too Small To Activate
- 4 - Failed To Operate
- 0 - Other
- U - Undetermined

Required if fire was within designed range

M4

Number of Sprinkler Heads Operating

|_____|

Required if system operated

M5

Reason for Automatic Extinguishing System Failure

- 1 - System Shut Off
- 2 - Not Enough Agent Discharged
- 3 - Agent Discharged But Did Not Reach Fire
- 4 - Wrong Type of System
- 5 - Fire Not In Area Protected
- 6 - System Components Damaged
- 7 - Lack of Maintenance
- 8 - Manual Intervention
- 0 - Other
- U - Undetermined

Required if system failed or not effective

NFIRS-9 Apparatus or Resources

A

72002	OK	12	17	2023	Station 6 (6)	2023-15905	0
FDID	State	Month	Day	Year	Station	Number	Exposure

B Apparatus/Resource	Dates/Times			Sent	Number of People	Apparatus Use	Actions Taken
ID: E1 Type: 11-Engine	Dispatch: Arrival: Clear:	12/17/2023 12/17/2023 12/17/2023	06:05 06:17 08:12	Sent	3	Suppression EMS Other	☐
ID: E4 Type: 11-Engine	Dispatch: Arrival: Clear:	12/17/2023 12/17/2023 12/17/2023	06:05 06:16 08:13	Sent	3	Suppression EMS Other	☐
ID: FD211 Type: 92-Chief officer car	Dispatch: Arrival: Clear:	12/17/2023 12/17/2023 12/17/2023	06:05 06:18 07:29	Sent	1	Suppression EMS Other	☐
ID: FD212 Type: 92-Chief officer car	Dispatch: Arrival: Clear:	12/17/2023 12/17/2023 12/17/2023	06:05 06:19 07:03	Sent	1	Suppression EMS Other	☐
ID: FD311 Type: 60-Support apparatus, other	Dispatch: Arrival: Clear:	☐ ☐ 12/17/2023 12/17/2023	 14:00 18:04	Sent	1	Suppression EMS Other	☐
ID: FD313 Type: 60-Support apparatus, other	Dispatch: Arrival: Clear:	☐ ☐ 12/17/2023 12/17/2023	 14:05 18:04	Sent	1	Suppression EMS Other	☐
ID: FD314 Type: 60-Support apparatus, other	Dispatch: Arrival: Clear:	☐ ☐ 12/17/2023 12/17/2023	 07:18 18:04	Sent	1	Suppression EMS Other	☐
ID: LAD6 Type: 13-Quint	Dispatch: Arrival: Clear:	12/17/2023 12/17/2023 12/17/2023	06:05 06:14 10:30	Sent	3	Suppression EMS Other	☐
ID: RES1 Type: 71-Rescue unit	Dispatch: Arrival: Clear:	12/17/2023 12/17/2023 12/17/2023	06:05 06:14 09:00	Sent	3	Suppression EMS Other	☐

ID:	SQD1	Dispatch:	12/17/2023	06:11	Sent	2	Suppression	
Type:	76-ALS unit	Arrival:	12/17/2023	06:21			EMS	
		Clear:	12/17/2023	07:26			Other	

ID:	SQD4	Dispatch:	12/17/2023	06:11	Sent	2	Suppression	
Type:	76-ALS unit	Arrival:	12/17/2023	06:22			EMS	
		Clear:	12/17/2023	07:10			Other	

ID:	SQD6	Dispatch:	12/17/2023	06:05	Sent	2	Suppression	
Type:	76-ALS unit	Arrival:	12/17/2023	06:58			EMS	
		Clear:	12/17/2023	07:33			Other	

NFIRS-10 Personnel

A

72002	OK	12	17	2023	Station 6 (6)	2023-15905	0
FDID	State	Month	Day	Year	Station	Number	Exposure

B Apparatus/Resource		Dates/Times			Sent	Number of People	Apparatus Use	Actions Taken
ID:	E1	Dispatch:	12/17/2023	06:05	Sent	3	☐ Suppression ☐ EMS ☐ Other	☐
Type:	11-Engine	Arrival:	12/17/2023	06:17				
		Clear:	12/17/2023	08:12				

Personnel ID	Name	Rank	Role	Attend	Actions Taken
103798	Berryhill, Dalton	FF / P			☐
103112	Okotoghaide, Jo'es	LT			☐
100887	HARRIS, TRENT	CPT			☐

B Apparatus/Resource		Dates/Times			Sent	Number of People	Apparatus Use	Actions Taken
ID:	E4	Dispatch:	12/17/2023	06:05	Sent	3	☐ Suppression ☐ EMS ☐ Other	☐
Type:	11-Engine	Arrival:	12/17/2023	06:16				
		Clear:	12/17/2023	08:13				

Personnel ID	Name	Rank	Role	Attend	Actions Taken
100131	BENNETT, JOHN	CPT			☐
101424	MIDDLESWART, RON	FF			☐
100614	EVANS, COLTON	LT			☐

B Apparatus/Resource		Dates/Times			Sent	Number of People	Apparatus Use	Actions Taken
ID:	FD211	Dispatch:	12/17/2023	06:05	Sent	1	☐ Suppression ☐ EMS ☐ Other	☐
Type:	92-Chief officer car	Arrival:	12/17/2023	06:18				
		Clear:	12/17/2023	07:29				

Personnel ID	Name	Rank	Role	Attend	Actions Taken
101651	PHILLIPS, BRANSON	CPT			☐

B Apparatus/Resource		Dates/Times			Sent	Number of People	Apparatus Use	Actions Taken
ID:	FD212	Dispatch:	12/17/2023	06:05	Sent	1	☐ Suppression ☐ EMS ☐ Other	☐
Type:	92-Chief officer car	Arrival:	12/17/2023	06:19				
		Clear:	12/17/2023	07:03				

Personnel ID	Name	Rank	Role	Attend	Actions Taken
101076	Johnson, Christopher	EMSO			☐

B Apparatus/Resource		Dates/Times			Sent	Number of People	Apparatus Use	Actions Taken
ID:	FD311	Dispatch:	☐	☐	Sent	1	☐ Suppression ☐ EMS ☐ Other	☐
Type:	60-Support apparatus, other	Arrival:	12/17/2023	14:00				
		Clear:	12/17/2023	18:04				

Personnel ID	Name	Rank	Role	Attend	Actions Taken
101016	HUGHES, CHRIS	Fire Marshal			☐

ID:	FD313	Dispatch: ☐ ☐	Sent	1	Suppression ☐
Type:	60-Support apparatus, other	Arrival: 12/17/2023 14:05			EMS
		Clear: 12/17/2023 18:04			Other

Personnel ID	Name	Rank	Role	Attend	Actions Taken
101893	SHARP, JUSTIN	FIRE INV			☐

ID:	FD314	Dispatch: ☐ ☐	Sent	1	Suppression ☐
Type:	60-Support apparatus, other	Arrival: 12/17/2023 07:18			EMS
		Clear: 12/17/2023 18:04			Other

Personnel ID	Name	Rank	Role	Attend	Actions Taken
102265	WENDLANDT, SCOTT	FIRE INV			☐

ID:	LAD6	Dispatch: 12/17/2023 06:05	Sent	3	Suppression ☐
Type:	13-Quint	Arrival: 12/17/2023 06:14			EMS
		Clear: 12/17/2023 10:30			Other

Personnel ID	Name	Rank	Role	Attend	Actions Taken
102949	Blocker, Garret	FF			☐
100171	BOECKMAN, JILL	CPT			☐
100922	HELLER, GERALD	FF / P			☐

ID:	RES1	Dispatch: 12/17/2023 06:05	Sent	3	Suppression ☐
Type:	71-Rescue unit	Arrival: 12/17/2023 06:14			EMS
		Clear: 12/17/2023 09:00			Other

Personnel ID	Name	Rank	Role	Attend	Actions Taken
101461	MOORE, JAROD	CPT			☐
101472	MORGAN, TREVOR	FF / P			☐
101909	SHERIDAN, JAKE	LT			☐

ID:	SQD1	Dispatch: 12/17/2023 06:11	Sent	2	Suppression ☐
Type:	76-ALS unit	Arrival: 12/17/2023 06:21			EMS
		Clear: 12/17/2023 07:26			Other

Personnel ID	Name	Rank	Role	Attend	Actions Taken
103790	Saied, Casey	FF			☐
101143	KINSEY, NATHAN	FF / P			☐

ID:	SQD4	Dispatch: 12/17/2023 06:11	Sent	2	Suppression ☐
					EMS

| Type: | 7t-ALS unit | Arrival: | 12/17/2023 | 06:22 | | | Other | |
| | | Clear: | 12/17/2023 | 07:10 | | | | |

Personnel ID	Name	Rank	Role	Attend	Actions Taken
101454	MOODY, DWIGHT	FF / P		....	⊔
102652	NORMAN, JORDAN	FF			⊔

ID:	SQD6	Dispatch:	12/17/2023	06:05		Sent	2	Suppression	⊔
								EMS	
Type:	7t-ALS unit	Arrival:	12/17/2023	06:58				Other	
		Clear:	12/17/2023	07:33					

Personnel ID	Name	Rank	Role	Attend	Actions Taken
101320	MARTIN, RUSTY	FF		. .	⊔
102472	GORDON, JOSEPH	FF / P		`	⊔

NFIRS-1S Supplemental

A

72002	OK	12	17	2023	Station 6 (6)	2023-15905	0
FDID	State	Month	Day	Year	Station	Number	Exposure

Primary Narrative:

All units dispatched and responded emergency status to a reported structure fire at the above address. Initial reports given to dispatch by bystanders stated they believed children lived in the house. They stated that there were no cars in the driveway and no one was standing outside of the residence. Reports also stated that the fire in the initial structure was starting to spread to an adjacent structure as well.

L6 arrived on scene first and gave an onscene and 360 report. L6 decided to employee a defensive strategy and began pulling defensive lines off L6.

R1 arrived on scene 2nd and went all in for VEIS of the survivable space of the exposure that was beginning to catch fire.

E4 arrived next on scene and established command.

Shortly after E4 arrived on scene, FD211 arrived and assumed command and asked for the incident commander to report to the command vehicle. E4 arrived at the command post and gave a report. E4 was then assigned exterior division with Sqd6 working for them. Their boundaries were the initial structure that was on fire. Their objective was fire extinguishment.

E1 was then assigned interior division of the exposure with L6 and Sqd4 working for them. After working for a short time Interior division stated that did not need Sqd4 working interior. Command then reassigned Sqd4 to the Exterior Division.

FD212 was assigned Medical Group Supervisor with Sqd1 working for them. Sqd1 was instructed to bring their cot to the command post and report to Med Group Supervisor. FD212 was then tasked with doing a 360 and reporting back to the command post. FD212's 360 report stated that the two structures were actually connected by a small breezeway. The majority of the fire was in the garage area with extension into the actual house portion of the structure.

R1 finished their primary VEIS search with no victims found. R1 was then reassigned to Ventilation Group and their objectives were to coordinate ventilation with Interior Division. The Vent group supervisor chose vertical ventilation and coordinated that with fire attack. After a quick stent in rehab, R1 was tasked with shutting down utilities.

As the scene was winding down, Sqd1 was reassigned to Interior Division with the objective of a Secondary Search.

Fire was declared under control and overhaul operations began. A deputy fire marshal and utility companies were requested.

Shift change occurred and crews were either released or rotated out. L6 and E4 remained on scene for overhaul operations.

Fire under investigation by Fire Prevention Division.

All units and equipment RTS.

Apparatus Narrative for E1:

Called to structure fire. On scene time delayed due to distance. U/A E1 was 4th suppression unit in behind L6, R1, & E4. We observed an approx. 2200 sq ft single story residential structure with heavy fire involvement in the Alpha/Delta corner and in the attic space throughout. E1 went to Command post for assignment and was assigned interior division.

L6 and R1 were currently doing interior FA with an 1 3/4" hoseline. They were pulling ceiling and making progress but due to advanced involvement in the attic I elected to keep L6 on FA and put R1 on vent. R1 made roof access and made a large vent hole to reduce any additional lateral fire involvement in the attic. I knew R1 VES the bedrooms but never heard a primary done so E1 completed a primary search of the structure while they were doing these tasks. We were then assigned SQ1. I had SQ1 do a secondary search of the structure. We ensured utilities were shut off as well. Approx. around the time the fire was extinguished we called and "all clear" from victim search.

We continued to do overhaul and search through the rubble in case of any potential victims. Once everything was under control the IC released E1 from the scene and dismantled the interior division. He then made L6 the overhaul group. E1 got their tools and equipment gathered up and went available. No further action taken.

Apparatus Narrative for E4:

E4 dispatched to structure fire. Report of possible exposure to adjacent structure. L6 on scene report reported similar findings. E4 arrives in the area and laid in from a hydrant 1 block north of the fire. There was a closer hydrant showing on ipad but had not heard any reports from L6 LT so we went ahead and took the hydrant due to the defensive nature of the fire and possibly two structures involved.

E4 on scene, assumed command briefly before 211 took over. E4 assignment was external Division with S6 and eventually S4 working with us. E4 took in their own hydrant. L6 had hand jacked to the closer hydrant 1 house west of fire. No booster backup was performed due to L6 being about ready to charge their hydrant by the time we made it in with ours. I made the decision with their small water tank, that it would have taken longer to booster backup at that time, than it would have for them to take in their own hydrant.

E4 pulled two 1 3/4" lines off the truck for exterior defensive operations on the Delta side of the structure. Resources were used to run two hose lines, and get utilities located and shut off. Fire knocked down quickly. Mopping up when C shift personnel arrived to take over.

Please note, i forgot to hit en route on this fire so my en route time is incorrect. Email sent that morning to BC as requested by dispatch when I called them.

Apparatus Narrative for LAD6:

Ladder 6 (B Shift) Narrative:

Ladder 6 was dispatched to the above location for a residential structure fire. Initial reports have conflicting information on victim status. Initial report states that there may be people and also vacant for three years. Initial report states that an exposure on the bravo side was also catching fire. Upon arrival Ladder 6 found the initial body of what was thought to be the initial house to be fully involved with the roof already collapsed. And found what was thought to be the Bravo side exposure to have heavy fire on the Alpha Delta corner. Ladder 6 immediately went in fast attack in the Bravo Side exposure. Pre-connect was pulled from Ladder 6. Ladder 6 Capt. did a 360 finding that it to be all one structure with a small hallway that connected the Garage portion of the house with the main living area. Ladder 6 then breached the locked door and entered through the Alpha side front door.

Rescue 1 did a coordinated VES search while the initial fire attack was being done.E4 was exterior supervisor. E4 pulled a pre-connect and attack the garage side of the fire. E1 was assigned to interior division supervisor with RES 1 Ladder 6. Primary Search was completed by Rescue 1. Sq. 6 was assigned to E4. Sq1 was reassigned from RIT/ Rehab to Secondary Search. Rescue 1 vented vertically. Fire was confirmed out and all searches were completed with an all clear. Salvage and Overhaul were completed and all hot spots were controlled. Oncoming shift was switched out with B shift crews and command was turned over to ladder 6. FD314 on-scene investigating. House appeared to be vacant with spray painted profanity on the walls. There was a gas can at the front door upon arrival and 2 on the back porch.

Apparatus Narrative for RES1:

R1 was dispatched as part of a full assignment to a residential structure fire. Initial reports were there were four people who lived in the structure, two were children, no one outside the structure per neighbor (RP). Enroute we could see flames and a large header of smoke from Lynn Lane between 51st and 41st. We arrived on scene behind L6 to find what was thought to be two separate structures. The first appeared to be fully involved with heavy fire now showing on the Alpha/Delta/Charlie end of the Bravo 1 exposure. R1 pulled past L6 to position closer to the exposure that was on fire with searchable space. L6 had setup Command and was in a defensive mode of operation. I met Command face-to-face in the front yard and advised we were going all in on a VEIS of the Alpha side of the B1 exposure. That was then broadcasted over FD211 to main and in coming units.

R1 firefighter entered the east bedroom window on the alpha side and assisted him with the TIC to isolate the door. Once isolated and search was underway, R1 Lt. entered the west bedroom window on the alpha side and again assisted with the TIC, anchoring both members from the window seal. Once R1firefighter completed searching the initial room, we bumped up to the hallway to look for victims and check the conditions. We were able to push across the hall to search the adjacent bedroom. R1 Lt. met us in the hallway and was able to search up to the living room area. Bathroom in the hallway also searched. We were then able to move up into the dining and kitchen area where we met fire attack coming through the front door. We were only able to search up to the doorway going into the hall/breezeway that was connecting the addition and garage because of heavy fire conditions. I was then able to give Command a complete on the primary search via FD 211.

I was then assigned as the Vent Group Supervisor and advised to Coordinate with Interior Division and fire attack. R1 was pulling ceiling to check for fire extension and there was heavy fire above running down the hallway. After checking the roof and conditions from outside via TIC and visual, it was apparent that the horizontal ventilation underway was not sufficient. Trench cut over the living/dining area coordinated with fire attack would keep the fire from progressing down the hallway over and past interior crews. I met Interior Division Supervisor inside and coordinated our plan of attack. R1 crew was assigned to the roof for ventilation. Ventilation was completed and conditions immediately began to improve. The progressing fire was then contained to the area above the kitchen and extinguished.

R1 crew reported to rehab for a quick cylinder change. I met face-to-face with Command and was reassigned to secure utilities. We were unable to find the gas meter and/or shutoff for the house. While searching we discovered that the weather head going to the utility closet on the back of the home had been burned and was exposed and hanging low near a rear exit and the utility closet. This was relayed to Command over FD211. The panel was located, and the main breaker was shutoff to the electric.

We were then advised to gross decontaminate and respond to Central to trade out with the C-shift crew and have them respond to assist in overhaul. After deconning our tools and PPE, we responded to Central and traded out with the oncoming crew.

Apparatus Narrative for SQD1:

Squad 1 arrived on scene and was assigned medical group and then moved to secondary search. We searched the east side bed room area of the structure and found no victims.
We then returned to service.

Apparatus Narrative for SQD6:

Sq6 was dispatched to a structure Fire, squad was staged one block north of the structure, in route potential of four victims was reported. Once on scene engine four requested assistance with a hydrant that they had one block north of the structure. Firefighter Martin, peeled from crew to assist with hydrant operations. FF Gordon assisted L6 hand laying LDH to a nearby hydrant, as they were calling for water. once opened and water was flowing to ladder 6.

Squad 6 was assigned to pull Cross lay and begin fire attack from the exterior. 1 3/4 smooth bore was deployed to the Charlie side and fire attack was commenced from exterior. Fire was brought under control. Gas cans were observed behind garage area and scene command was notified. Returned to service JG