REGISTERED LAND SURVEYOR'S INSPECTION PLAT AND CERTIFICATE FOR MORTGAGE LOAN PURPOSE

COLLINS LAND SURVEYING, INC.
3340 W. 151st ST. S. – P.O. Box 250
KIEFER, OK. 74041
OFFICE (918)321-9400 FAX (918)321-9404

J.O. NO.: 17-05-132
Customer: First American Title & Trust Company
Borrower: McCleary, Lois R.
2241736-TU02
Plat No: 3293

B/L=Building Line U/E=Utility Esmt. F/E=Fence Esmt.	OB/L-Out Building Line SW/E=Sidewalk Esmt. R/W=Right of Way	D/E=Drainage Esmt. B/E=Buried Tele. & Elec. Cable Esmt. S/E=Service Entrance	SCALE: 1"=30' NORTH

SUBJECT PROPERTY LIES WITHIN FLOOD ZONE "UNSHADED X" AN AREA OF MINIMAL FLOOD HAZARD AS SHOWN ON FIRM MAP#400236 0456L, DATED 10/16/2012.



THIS PLAT IS MADE FOR AND AT THE REQUEST OF: First American Title & Trust Company / Gateway Mortgage Group, LLC, ISAOA/ATIMA

FOR MORTGAGE LOAN PURPOSES ONLY COVERING LEGAL DESCRIPTION AS PROVIDED

Lot Forty-eight (48), Block Two (2), COUNTRY CLUB ESTATES ADDITION to the City of Broke Arrow, Tulsa County, State of Oklahoma, according to the recorded Plat No. 3293.

Property address: 8202 South Ash Avenue, Broken Arrow, Oklahoma

SURVEYORS STATEMENT