City of Broken Arrow

Drainage Advisory Committee



PROJECT REPORT

DATE:	8//22
NAME	Len Villalon
ADDRESS / LOCATION	46 Cedar Ridge Road
WATERSHED	Haikey Creek
ESTIMATE	\$80,000.00
CASE NO.	

DESCRIPTION

Cedar Ridge Estates subdivision is West of Garnett Road and North of Florence St and was platted in 1971. The Reserve Area is platted as a drainage easement. However, the reserve area is privately owned. It was initially sold by the developer at the same time to the same person who purchased Lot 16 in 1984, Lot 16 and the reserve are is currently owned by Mr. Villalon.

The original design outlet of the culvert under Cedar Ridge Road was to an open ditch. A junction box was added to the downstream culvert connecting the cross road culvert and the driveway culverts on the west side of Cedar Ridge Road. The pipe out-letting from the junction box is a private 30 inch corrugated metal pipe. The private pipe is failing and causing sink holes in the reserve area. The failing pipe could cause a blockage and back water up onto Cedar Ridge Road.

Stormwater runoff from approximately 10 acres of the Cedar Ridge Estates subdivision drains through the reserve area. The 10 acres generates about 30 cfs of flow.

The estimated construction cost for the project is \$80,000.00 in 2024 dollars.

The original case no. is 22-002 presented on 02-28-2022.

BENEFIT

Repair drainage way downstream of the culvert under Cedar Ridge Road to protect the roadway.

RECOMMENDATION

Staff recommends approval of \$80,000 for construction of drainage improvements downstream of the Cedar Ridge Road Culver.

COMPLETED BY: Chuck Collins DATE: 8/22/2023

Rev. 1 02-05-21

City of Broken Arrow

Drainage Advisory Committee



APPLICATION

DATE:	August 22, 2023
OWNER NAME:	City of Broken Arrow
PHONE NUMBER:	
EMAIL ADDRESS:	
OWNER MAILING ADDRESS:	
ADDRESS OF PROPERTY WITH DRAINAGE PROBLEM:	46 W Cedar Ridge Road, Broken Arrow, OK 74011
LOCATION OF DRAINAGE ISSUE ON PROPERTY:	Reserve lot north of above address.

DESCRIPTION OF PROBLEM: (*PHOTOS SHOULD ACCOMPANY APPLICATION)

Cedar Ridge Estates subdivision is West of Garnett Road and North of Florence St and was platted in 1971. The Reserve Area is platted as a drainage easement. However, the reserve area is privately owned. It was initially sold by the developer at the same time to the same person who purchased Lot 16 in 1984, Lot 16 and the reserve area is currently owned by Mr. Villalon.

The original design outlet of the culvert under Cedar Ridge Road was to an open ditch. A junction box was added to the downstream culvert connecting the cross road culvert and the driveway culverts on the west side of Cedar Ridge Road. The pipe out-letting from the junction box is a private 30 inch corrugated metal pipe. The private pipe is failing and causing sink holes in the reserve area. The failing pipe could cause a blockage and back water up onto Cedar Ridge Road.

Stormwater runoff from approximately 10 acres of the Cedar Ridge Estates subdivision drains through the reserve area. The 10 acres generates about 30 cfs of flow.

SIGNATURE:	

RETURN TO STORMWATER DIVISION MANAGER'S OFFICE, PO BOX 610 Broken Arrow, OK 74013

Rev. 1 05-08-2020











& GDU 5. GH & EGLYLVLRQ RFDWLRQ



& GDU 5. GH & EGLYLVLRQ RFDWLRQ





PHOTOGRAPH LOG




Figure 1 West Property line looking east



Figure 2 Outfall looking west



Figure 3 Outfall



Figure 4 Sinkhole Picture



Figure 5 Sinkhole Picture



Figure 6 Cedar Ridge Rd culvert - upstream



Figure 7 Cedar Ridge Rd Culvert - downstream