City of Broken Arrow

Drainage Advisory Committee



PROJECT REPORT

DATE:	June 24, 2025
NAME	Tyler Yoak
ADDRESS / LOCATION	Indian Springs County Club
WATERSHED	Arkansas River (Elm Creek)
ESTIMATE	\$125,000
CASE NO.	25-015

DESCRIPTION

Indian Springs Country Club is experiencing erosion on the golf course where a 48-inch pipe daylights out of the hillside between #8 and #6 fairway. The pipe collects water from the subdivision to the north. The pipe has broken apart in several places and is disconnected from the headwall. This appears to be causing downstream erosion along the hillside. Within the past 3 months, there has also been flooding in the neighborhood to the north, Indian Springs 2nd Addition. This subdivision connects to broken drain pipe, likely causing the stormwater to be impeded. The City spoke with the residents in the neighborhood, and it has been noted that the problem was worse than ever this past spring. There has been record rainfall the past several months. The downstream condition of the pipe could also be a contributing factor of the flooding in the Indian Springs neighborhood. Another possible contributing factor to the street flooding is there is one inlet on the south side of Fairway Dr. that collects approximately 5 acres from the subdivision. The water on the north side of Fairway Dr. ponds and eventually evaporates or drains to the inlet on the south side of Fairway Dr.

Staff is requesting \$125,000.00 for survey and construction funds. Design will be conducted in house.

Case No. 25-015

BENEFIT

Mitigate the erosion and street flooding in the Indian Springs 2nd Addition subdivision and on the Indian Springs Golf Course.

RECOMMENDATION

Approve the request for expenditure of \$125,000 for survey and construction funds for drainage improvements of the public storm system in the Indian Springs 2nd Addition neighborhood and along the Indian Springs Golf Course.

COMPLETED BY: Sarah Walters

DATE: 6/23/2025

Walters, Sarah

From: Sent: To: Subject: Wilson, Patrick Monday, June 23, 2025 9:48 AM Walters, Sarah FW: *NEW SUBMISSION* Drainage Advisory Committee Project Application

Patrick Wilson, P.E., CFM

Stormwater Division Manager Engineering and Construction Department

City of Broken Arrow

485 N. Poplar Ave. Broken Arrow, OK 74012 Office: 918-259-7000 ext. 5243 | Fax: 918-259-8453 pwilson@brokenarrowok.gov | www.brokenarrowok.gov



This message is intended only for the use of the individual or entity to which it is addressed and may contain information that is privileged, confidential and, exempt from disclosure under applicable law. If you receive this message in error, you are hereby notified that the City of Broken Arrow does not consent to any reading, dissemination, distribution or copying of this message. If you have received this communication in error, please notify the sender immediately and destroy the transmitted information immediately.

From: BrokenArrowOK.gov webmaster <webmaster@brokenarrowok.gov>
Sent: Saturday, June 21, 2025 10:45 AM
To: Wilson, Patrick <PWilson@brokenarrowok.gov>; Engineering & Stormwater
<engineering.stormwater@brokenarrowok.gov>
Subject: *NEW SUBMISSION* Drainage Advisory Committee Project Application

Drainage Advisory Committee Project Application

 Submission #:
 4133909

 IP Address:
 172.59.124.132

 Submission Date:
 06/21/2025 10:44

 Survey Time:
 1 day, 3 minutes, 51 seconds

You have a new online form submission. Note: all answers displaying "*****" are marked as sensitive and must be viewed after your login.

Owner Name

Tyler Yoak

Phone

(918) 630-4480

Email

tyoak@indianspringsclub.com

Owner Mailing Address

PO Box 3367 Broken Arrow, OK 74013

Address of Property with Drainage Problem

16006 E 131st St S Broken Arrow, OK

Location of Drainage Issue on Property

Between the #8 and #6 fairways on the River course. Near where the unnamed south-running road spur comes off of Fairway Dr.

Description of Problem

48" drain pipe comes out of hillside between #8 and #6 fairways. This pipe almost entirely receives stormwater from the neighborhood to the north. As stormwater has increased, the load on the pipe caused it come off of its footing and disconnect from the weir. Because of this, stormwater does not follow the intended flow and has caused significant erosion to the hillside. With the significant rains we've had in the past 3 months, there has been flooding in the neighborhood to the north that uses this drain pipe, likely because drainage is impeded. After speaking with concerned residents whose properties flooded, they said it was worse than ever now. The BA Stormwater Project Manager visited the site and she agrees it's a dangerous situation. We put up a warning fence to keep people away from the gulch it has created but with the recent waters, the erosion has worsened, eating away more of the hill, causing our fence to collapse into the hole.

Please attach photos depicting the Drainage Issue

Erosion1.jpg Erosion2.jpg Erosion3.jpg Erosion4.jpg

Thank you, City of Broken Arrow

This is an automated message generated by Granicus. Please do not reply directly to this email.




Google Earth

Image © 2025 Airbus

Stormwater Utility Map



6/24/2025 2:54 PM



Ο

BMP Point

💽 Unknown

O Detention

O Dry Basin

O Treatment


🚫 Wet Basin

Bed Filter

This map's utility information is for general purposes only. The City of Broken Arrow makes no warranties regarding its accuracy, completeness, or reliability. Use of this information is at risk. 0 0.03 0.05 0.1 mi

Maxar, Microsoft, Copyright nearmap 2015, City of Tulsa, US Census Bureau, INCOG, & unknown, Esri Community Maps Contributors, City of Tulsa, Texas Parks &





CAPTURICATE OF DEDICATION --INDIAN SPRINGS CROCKED ADDITION. WHERE, INCLUS SPRING ENTATES, 200., an Uklahume Corporation, is sense of the following described last in the Chu Tales, Saids of Glabume, build

> The Derthwest Derter of Bestins 11 Denne (4) 21 15 5 for 19.10 forth Denne 5 (4) 11 15 for 19.10 forth Denne 5 (5) 10 for 115 5 forth Denne 100 [] All feets from 1724 and the second s freet. Thennes along a narra to the freet. Thennes a not not not a for a thennes a day alor after 473.5 (5.030) mores are as last.

The initialized of the provident of the set of the set of the set of the last devery definite for public use a there is and plat and does hering gargante the fills to all of the last covered by fair streats, and for the orderly found on the above described fead added, and is order to provide adapted be addressed as the orderly defined on the above described fead added, and is order to provide adapted be addressed as a orderly defined on the above described fead address of the fair to be the start of the orderly defined for the above of the set of the definition of the set of the definition of the set of the definition of the set of the definition of the set of the definition of the set of the sublic use all

These coverents are to you with the lave and shall be binding on all parties and all persons stating under them shall be estimated for example of the first person with the estimated of end of the (10) years, unless by work of a state of the state of th

eres, or the assigns, shall visians ar attempt to visians any of the corretants herein, it shall be lastic persons availing any real property situated in said development of subtrivision to proceedings has the period of the sense or persons visialing or attempting to the initiate any many consumts and either to p so fains or to recover damages or alter does for such visialization. INVALING of any new of these news i order shall in her way affect any of the other provisions which wail remains the full forest and while response to the provisions which wail remains the full forms and without the sense and withou

Deplication of place will be permitted only where there is at least four nonexpites (lots) between locations for such any institutions. Conjustion of floor plan with a complete shange of enterior styling will be permitted where at least pro-

They in the treat shall be known and described as replacedial homesites. By signature shall be sreated, altered, permitted to remain on any homesite which erecain two sizers is height, and all realizences must have a private (but ices than its ward attacted to the remain two sizers is theight, and all realizences must have a private storage heliding, correct entertainment arms, storage is private to be helid or the homesing with attact of and structures and he minimised arms, shall confure to the helid of the desiling forman. Altered attactions and structures and he minimised arms, their confuse to the helid of the desiling formants.

No Welling or part thereof, strept over purches and terrance shall be constructed and maintained on any the front property lies then the Welling liese shown on the recorded visit of said shifting, and no rest manyor them. Let. (2) frest to any pile lot lies on pus tile and thesize (12)feet on the other slis, thus total of at least teenty (2) feet between the residence and both side lot lines. new shall be built

Place area requirements. All square footner requirements are stalueive of serares and purches. All homesites shall neve a staleme of 2000 square foot of living area (measured over measure), for one stary residence. For sen stary or one and one taid stary residences a minimum of 1000 spunse fast will be required on the growni floor. with a total of 2000 square feet.

7. a. All errored foundations shall be of brick or state. In nonspote light, pourel constate as any other foundation

any other roofing anterials recommended to be used must be approved by the Covelager puter to dart of construction. Betype, covalese and estaviat millsork will be classiv examined to induce sound graditectoral graditude. No petal

any bind shall be displayed to the public view on any lot encould one professional size of not wave than file groups fast advertising the property for sale or pant, o


its will be used for the storage of meterials for a period of greater than 30 days prior the sampling shall be achieved within 7 months, all homestics shall be achieved the samplement of the


to of sometructing, said tary sever, telephone 12 evaluation for mash of the these down on and that fight of ma backs, lay and relay where limit and eparture to the start start and and/or example to the relaying

. 19.2% at Dilss, Dilss County, Calabora

ST.

Herry











Recent rains have caused erosion to accelerate. This Fence was installed over a year ago with ample room between it and the gulch below. But early in June the erosion advanced and the fence fell into the valley below. This not only shows the rapid erosion to the property, but presents a major safety concern as there is a fairway at the top of this hill.





