2016 - 2017 AUCTION LIST		
ription	Notes	Οι
Ford Crown Victoria	Replaced, Paint,Right marker lamp, No rear seat	5/2
Ford Crown Victoria	Engine has knock noise. Dept. declined repairs	10
Ford Crown Victoria	Transmission was stuck in high gear when removed from service. Department declined repairs	5/2
Ford Crown Victoria	Engine has bad headgasket and burns coolant, Paint peel and rust, drivers seat has tears	3/9
Ford Crown Victoria	Needs transmission. Dept. declined repairs, Paint peel and rust	3/1

Asset	Unit#	VIN#	Odometer	Department	Description	Notes	Out of service date		
00004500	578	2FAFP71W45X176257	115,652	Police Dept.	2005 Ford Crown Victoria	Replaced, Paint,Right marker lamp, No rear seat	5/20/2015		
00004271	434	2FAFP71W14X151895	176,320	Police Dept.	2004 Ford Crown Victoria	Engine has knock noise. Dept. declined repairs	10/18/2016		
				-		Transmission was stuck in high gear when removed from service.			
00003749	0348	2FAFP71W73X199402	126,919	Police Dept.	2003 Ford Crown Victoria	Department declined repairs Engine has bad headgasket and burns coolant, Paint peel and rust,	5/20/2015		
00003741	0341	2FAFP71W33X199385	132,200	Police Dept.	2003 Ford Crown Victoria	drivers seat has tears	3/9/2016		
00004266	0429	2FAFP71W54X151902	142,728	Police Dept.	2004 Ford Crown Victoria	Needs transmission. Dept. declined repairs, Paint peel and rust	3/10/2016		
00004894	0747	2FAFP71W27X145656	137,488	Police Dept.	2007 Ford Crown Victoria	Transmission needs rebuilt. Only has reverse			
00004505	0581	2FAFP71W35X176265	116,665	Police Dept.	2005 Ford Crown Victoria		7/22/2016		
NONE	8001	13YFS1015LC033189		Police Dept.	1990 Starlight 510NT enclosed trailer	Replaced	10/17/2016		
	8014	1GCDC14H4KZ234915	131,350	Police Dept.	1989 Chevrolet Pick up	Replaced	12/9/2016		
	8091	943507218B		Police Dept.	1983 Horse trailer	Replaced	12/9/2016		
00002733	9781	4S7CT0994VC023971	9017 hrs	Fire Dept.	1997 Spartan fire truck	Transfer case need replaced/rebuilt	6/28/2016		
00003560	0208	26483		Street Dept.	2002 Valk 11ft Snow Plow	Bent	1/26/2016		
00003695	0327	27464		Street Dept.	2003 Valk 11ft Snow Plow	Replaced	1/26/2016		
00003690	0328	27465 03018378		Street Dept. Street Dept.	2003 Valk 11ft Snow Plow 2003 Monroe Sander MSV-144-84-56	Replaced Panlaced	1/26/2016 1/26/2016		
00003700	0336	03018380		Street Dept.	2003 Monroe Sander MSV-144-84-56	Replaced Replaced	1/26/2016		
00003700	0337	03013879		Street Dept.	2003 Monroe Sander MSV-144-84-56	Replaced	1/26/2016		
None	None	A18677		Street Dept.	RKI service body model L60DW1294	Replaced by flat bed	6/23/2006		
00003536	0185	1C9ED122911418335	2484 hrs	Street Dept.	Crafco Asphalt crack sealer	Fire box needs rebuilt	10/27/2016		
None	1390	PS424H-700374-AAA		Storm Water	2013 Simpsom Power Washer	Engine is seized up	6/22/2016		
00002035	1016	100984		Storm Water	1994 Public Health Mosquito Sprayer	Replaced	6/30/2016		
00004529	0546	RSF00124		Storm Water	2005 ASV RC85	Engine has low compression and will not start.	1/20/2016		
00002402	0725	1ETDE1770VIV.C77492	157.010	W Milliel	1007 Ford F 150	Engine has loud knocking noise. Torn head liner, Department	2/20/2014		
00002402 00000706	9725 262	1FTDF1769VKC77483 T1089	157,019	Water Utilities Water Utilities	1997 Ford F-150 1981 Belshe T2 Trailer	decided not to repair Needs Axle	2/20/2014 12/22/2015		
0000706	9512	1FTEX14H0SCK09169		Water Offittes Water Plant	1995 Ford 1/2Ton Pickup	Transmission leaking fluid. Department declined repairs	7/5/2016		
00002110	7512	11 1221 1110501107107		Witter Film		Power Train Control Module, Engine Overheats, Department	113/2010		
00003038	0023	1B7GL22X2YS738006	130,432	Meter Reading	2000 Dodge Dakota	refused repairs	8/29/2013s		
00003721	0316	48X1F392131002413		Waste Water Plant	2003 Travis 39foot end dump trailer	Replaced	10/18/2016		
00002209	9604	1HTSHAAR9TH279512		Parks Dept	1996 IHC 4900 Dump Truck	Engine seized up. #2 cylinder piston seized up	6/22/2016		
00003242	0119	1FDWF36S21EB15587		Parks Dept.	2001 Ford F-350 with Reading Utility bed.	Needs fuel pump. Battery, Transmission Cooler leaks fluid, Power steering leaks fluid Department declined repairs	6/22/2016		
00002116	9512	1FTEX14H0SCC09169	87937	Parks Dept.	1995 Ford F-150 4X4	Replaced. Needs transmission	10/18/2016		
00004207	0400	1FDWF36L54EB52534		Parks Dept.	2004 F-350 with Wayne Trash hauler	Needs front end repair	10/31/2016		
00005543	0946	29000494		Parks Dept.	2009 Toro Utility Cart	Needs rear end repairs	11/2/2016		
NONE	1108	1011040126		Signal Maint.	2011 Ingersole Rand Compressor	Engine is locked up	5/5/2015		
00003082	0105	1B7HC16Y71S771462		Fleet pool unit	Dodge Ram 1500	Transmission slips between shifts when operating. Department decided not to repair	6/23/2015		
00002741	9922	1FTRF17W1XKC04665		Fleet Pool Unit	1999 Ford Crown Victoria	Odometer is not operational	1/30/2014		
00005545	0948	D070222		Fleet Maintenance	2009 Gardner Denver Compressor	Unit was running when removed from service	3/7/2016		
00002110	9505	2FTEF15N6SCA59080	67,748	Operations	1995 Ford F-150	Intake manifold leak, needs tune up, slight cylinder misfire under light load. Seats torn Bed rust Dash is broke.	10/17/2016		
n/a	n/a	n/a	07,740	Parks	3- 2 drawer file cabinets	Replaced	10/17/2010		
					150 Black folding chairs,40 wood folding				
n/a	n/a	n/a		Parks	chairs,Dancefloor	Replaced			
n/a n/a	n/a n/a	n/a n/a		Parks Parks	Pool table Office desk	Replaced Replaced			
n/a	n/a	n/a		Fire	Shoulder press machine	Replaced			
n/a	n/a	n/a		Fire	Precor Treadmill	Replaced			
n/a	n/a	n/a		Development Services	6 Office chairs	Replaced			
n/a	n/a	n/a		Sewer	Wood desk	Replaced			
n/a	n/a	n/a		Sewer	Qty.3 5HP electric motors	Replaced			
n/a	n/a	n/a		Sewer	Qty.3 15HP electric motors	Replaced			
n/a	n/a	n/a		Sewer	1.5 HP electric motor	Replaced			
n/a	n/a	n/a		Sewer	7.5 HP electric motor	Replaced			
n/a	n/a	n/a		Sewer	10 HP electric motor	Replaced			
	2016 2017 AUCTION LICT CONTINUED								

n/a	2007	n/a		Sewer	Homelite smoke blower mod. 111B-1	Replaced	
00000676	n/a	n/a		Sewer	3HP Electric Motor w/valutes and fittings	Replaced	
n/a	n/a	n/a		Sewer	18 assorted pulleys for electric motors	Replaced	
n/a	n/a	n/a		Sewer	Qty.2 10HP electric motors	Replaced	
4404	n/a	n/a		Sewer	HP Printer 44D4	Replaced	
n/a	n/a	n/a		Cemetery	36" Dayton exhaust fan	Replaced	
n/a	n/a	n/a		Police	5 Office chairs	Replaced	
n/a	n/a	n/a		Police	1 6' Table	Replaced	
n/a	n/a	n/a		Police	1 8' Table	Replaced	
n/a	n/a	n/a		Police	Metal desk top	Replaced	
2499	n/a	n/a		Police	Filing cabinet	Replaced	
2151	n/a	n/a		Police	Filing cabinet	Replaced	
n/a	n/a	n/a		Police	2 sets of lockers	Replaced	
n/a	n/a	na		City Manager	1 painting		
n/a	n/a	n/a		City Manager	Reception desk	Replaced	
n/a	n/a	n/a		City Manager	Cloth wall blind	Replaced	
n/a	n/a	n/a		City Manager	2 Metal cabinet	Replaced	
n/a	n/a	n/a		City Manager	2 Office chairs	Replaced	
n/a	n/a	n/a		Human Resources	4 Office chairs	Replaced	
00003049	n/a	n/a		Water	HP laserjet 8000N printer	Replaced	
n/a	n/a	n/a		Legal	2 Brief cases	Replaced	
n/a	n/a	n/a		Legal	Assortment of 4 paintings	Replaced	
2529	n/a	n/a		Legal	4 drawer file cabinet	Replaced	
2530	n/a	n/a		Legal	4 drawer file cabinet	Replaced	
n/a	n/a	n/a		IT	Equipment rack w/3 channel combiner (edacs)	Replaced	
n/a	n/a	n/a		IT	Decibel amplifier WD18312	Replaced	
n/a	n/a	n/a		IT	Decibel power supply DB8980P	Replaced	
n/a	n/a	n/a		IT	Sentry power supply DB8860	Replaced	
n/a	n/a	n/a		IT	91430-01 Equipment shelf	Replaced	
n/a	n/a	n/a		IT	Standard ground kit GK-S400T Qty.6	Replaced	
n/a	n/a	n/a		IT	Tesco antenna dish HPLP1 Qty.2	Replaced	
n/a	n/a	n/a		IT	Misc. connecter cables	Replaced	
n/a	n/a	n/a		IT	Motorola radio mount Qty. 2	Replaced	
n/a	n/a	n/a		IT	Zetron fire alert panel	Replaced	
n/a	n/a	n/a		IT	Micor repeater w/exiter and amp	Replaced	
n/a	n/a	n/a		IT	Motorola plus 600 series power supply Qty.2	Replaced	
n/a	n/a	n/a		IT	Megaplex 2104 multiplier	Replaced	
n/a	n/a	n/a		IT	Megaplex multiplier card	Replaced	
n/a	n/a	n/a		IT	Zgxel Modem Qty. 3	Replaced Replaced	
11/a 4946				IT			
4946	n/a	n/a	l	11	Air max 200 microwave w/mounting kit	Replaced	Ī.