## 66,000 GVW Tractor/trailer cab & chassis 50 Ton Trailer Bid# 17.123

Bid opening 11-23-16

Bid opening 11-23-16						
<b>1</b>	Summit Tour!	Doods Toronto	Description Translation	Province Tours Is #1	Describer on Toronto	
Item	Summit Truck	Rush Truck	Premier Truck #2	Premier Truck #1	Bruckner Truck	
Specification	2017/18 International 6x4 Tandum	2017 Peterbilt 567	2018 Freightliner 114SD	2018 Westen Star 4700SB	2018 Mack GU713	
66,000 GVW Tractor/trailer cab & chassis	\$104,911.67	\$108,320.00	\$108,812.00	\$113,757.00	\$128,256.00	
Options						
Larger engine	\$1,800.00	\$0.00	\$500.00	\$350.00	\$3,036.00	
Auxiliary switches	\$552.00	\$70.00	\$136.00	\$136.00	\$137.00	
Keys	\$0.00	\$6.00	\$0.00	\$0.00	\$2,027.00	
Fob	\$218.00	\$157.00	n/a	n/a	n/a	
Power windows/locks	\$207.00	\$0.00	\$200.00	\$200.00	\$422.00	
Front tow hooks	\$73.00	\$0.00	\$75.00	\$75.00	\$0.00	
Trailer connection kit	\$500.00	\$132.00	\$0.00	\$0.00	n/a	
5th wheel	\$0.00	\$1,360.00	\$0.00	\$0.00	\$2,900.00	
Hydraulic wet kit	\$6,419.95	\$7,410.00	\$6,412.00	\$6,412.00	\$9,356.00	
Total	\$114,681.62	\$117,455.00	\$116,135.00	\$120,930.00	\$146,134.00	
Meet Specs.	Yes	Yes	Yes	Yes	No	
Delivery	90 days	84 days	60 days	60 days	120 days	
Warranty	1vr/ unlimited	1yr/ 100k,engine 2yrs/250k, transmission 3yr/unlimited	2yr/250k	2yr/250k	2yr/250k	
	Tyl/ diffillited	3yi/ummmed	2y1/230K	2y1/230K	2y1/230K	
Bids sent to 9 vendors  Notes	Truck meets specifications. Vendor is quoting the International Engine. Past history shows that this engine was not a reliable choice. Excessive down time has been associated with the International product.	Truck meets specifications. Product has been a reliable vehicle. No reported down time issues. Vendor has offered the optional larger engine at no cost.	Truck meets specifications Product has been a reliable product. Only problems are returning vehicle to Service Dept. for repeat or repairs not completed which results in excessive down time.	Truck meets specifications City of Broken Arrow only has 1 vehicle in our fleet of to make an evaluation. Issues with the Service Dept. Repeat repairs.	Truck does not meet specifications. Rear Suspension,, No manuals or parts book offered	

