

Bid 17.128
Tandem Roller w/Dual Drums
Bid Date 01/18/2017

| Item | Oct Equip. | Brownco | Whitestar | Kirby-Smith Exchange | Warren Cat |
|----------------------------|---|--|---|---|--|
| Specification | 2017 Case DV26 | 2016 Bomag BW120 SL-5 | Bomag BW120 SL-5 | 2017 Hamm HD12VV | 2017 Cat CB24B |
| Tandem Roller w/Dual Drums | \$33,273.00 | \$34,079.00 | \$37,412.00 | \$40,503.00 | \$42,371.00 |
| Options | | | | | |
| Folding canopy | \$0.00 | \$1,765.00 | \$0.00 | \$0.00 | \$810.00 |
| Cup holder | n/a | \$0.00 | \$0.00 | \$0.00 | \$61.00 |
| Dual propel levers | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$865.00 |
| Sliding seat | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| Battery disconnect switch | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| Total | <u>33,273.00</u> | <u>35,844.00</u> | <u>37,412.00</u> | <u>40,503.00</u> | <u>44,107.00</u> |
| Meet specs | <u>N</u> | <u>N</u> | <u>N</u> | <u>N</u> | <u>N</u> |
| Notes: | Drum width and diameter does not meet minimum spec. No cup holder option available | Unknown Horse Power Drum width and diameter does not meet minimum spec. | Year model not identified Horse power does not meet minimum spec. Drum width and diameter does not meet minimum spec. | Horse power does not meet minimum spec. Drum width does not meet minimum spec. | Drum width does not meet minimum spec. |
| Delivery | 30-120 days | 7-42 days | 30-60 days | 60-90 days | 112 days |
| Warranty | 1 yr | 1 yr | 1 yr | 1 yr/12K | 1 yr/1500 hrs. |

This bid tabulation is true and accurate to the best of my knowledge

Thursday, January 26, 2017



Patrick Harrison

Purchasing Manager