

Fritz Land Surveying, llc

Professional Land Surveying Services

APPLICATION EXHIBIT C

APRIL 22, 2015

PROPERTY ADDRESS: 4312 SOUTH RETANA AVENUE, BROKEN ARROW, OK 74011

SURVEYOR'S CLIENT: SCOTT & SIDNEY WEBB / SZAFRANSKI PUGH & ASSOCIATES

PARENT TRACT LEGAL DESCRIPTION AS PROVIDED IN JOINT TENANCY WARRANTY DEED FILED AS DOC. #2011026444: LOT ONE (1), BLOCK FOUR (4), BERWICK ON CEDAR RIDGE, BLOCKS 2, 3, 4, 5 & 6, A SUBDIVISION IN THE CITY OF BROKEN ARROW, TULSA COUNTY, STATE OF OKLAHOMA, ACCORDING TO THE RECORDED PLAT THEREOF.

2017 W. 91st Street Tulsa, OK 74132

Ph: 918.231.0575

Email: fritzpls@yahoo.com

www.fritzlandsurveying.com