


DOC #1

Existing Lots


PLAT OF SURVEY

¶ EAST FREEPORT STREET



DEC 31 2019

RECEIVED



LOCATION MAP

TOPOGRAPHIC LEGEND

- CHAINLINK FENCE
- MONUMENT FOUND
- MONUMENT SET

0 30 60

1" = 30



Surveyor's signature is not
required, the plan is a copy
that should be assumed to contain
unauthorized alterations. The
certification contained on this
document shall not apply to any



DATED: 12/05/2019

Last Date of Survey: 12/04/2019


LEMKE LAND SURVEYING, LLC	Surveyed By: JL / ER	Project: PLAT OF SURVEY ORIGINAL TRACT	Sheet Number
S L	Drawn By: RLR	W40' LOT 2 & ALL LOT 3 BLK 6 COLLEGE ADD.	
L S	Approved By: CDC	Project Location: 315 EAST FREEPORT STREET	
	Date: 12/05/2019	BROKEN ARROW, OKLAHOMA 74012	
	Scale: 1" = 30'	Client: BORN AGAIN RESTORED	
	Project No: 19609	304 EAST COMMERCIAL STREET	1
			Sheet 1 of 2

DOL #2

Proposed Lot Split

PLAT OF SURVEY

@ EAST FREEPORT STREET




SURVEYOR'S CERTIFICATION:

I, Charles D. Cahill, do hereby certify that I or those under my direct supervision have performed a careful survey of the property as shown by the annexed plat. I further certify that this survey meets or exceeds the Oklahoma Minimum Standards for Land Surveying.

LEGAL DESCRIPTION: Tract A: The West Forty (45) feet of Lot Three (3), Block Six (6), COLLEGE ADDITION to the City of Broken Arrow, Tulsa County, State of Oklahoma, according to the Recorded Plat No. 37.

Tract B: The West Forty (40) feet of Lot Two (2) and the East Five (5) feet of Lot Three (3), Block Six (6), COLLEGE ADDITION to the City of Broken Arrow, Tulsa County, State of Oklahoma, according to the Recorded Plat No. 37.



LOCATION MAP

TOPOGRAPHIC LEGEND

- CHAINLINK FENCE
- MONUMENT FOUND
- MONUMENT SET

0 30 60

1" = 30



If the Surveyor's signature is not
red ink, the plan is a copy
that should be assumed to contain
unintended alterations. The
certifications contained on this
document shall not apply to any
copies.

CITY OF BROKEN ARROW

DEC 31 2019

RECEIVED

12/05/2019

Last Date of Survey: 12/04/2019

LEMKE LAND SURVEYING, LLC
S L
L S
7080 YALE AVE, STE. 603, TULSA, OK 74136
PH.(918)895-0363 FAX(918)895-0363
CA # 6975
http://www.lemke-llc.com

Surveyed By: JL / ER	Project: PLAT OF SURVEY TRACT A & TRACT B
Drawn By: RLR	
Approved By: CDC	Project Location: 315 EAST FREEPORT STREET BROKEN ARROW, OKLAHOMA 74012
Date: 12/05/2019	Client: BORN AGAIN RESTORED 304 EAST COMMERCIAL STREET
Scale: 1" = 30'	
Project No: 19609	

Sheet Number
2
Sheet 2 of 2