



SYMBOL LEGEND

- Fence Line (All Types)

Monuments found and used for this survey (various types)
3/8" Iron Pin set w/cap 'REED'

LEGAL DESCRIPTION OF THE REAL PROPERTY

LOT ELEVEN (11), BLOCK ONE (1), DODSON ADDITION TO BROKEN ARROW, TULSA COUNTY, STATE OF OKLAHOMA, ACCORDING TO THE RECORDED PLAT

THE WEST HALF (W/2) OF LOT ELEVEN (11), BLOCK ONE (1), DODSON ADDITION TO BROKEN ARROW, TULSA COUNTY, STATE OF OKLAHOMA, ACCORDING TO THE

THE EAST HALF (E/2) OF LOT ELEVEN (11), BLOCK ONE (1), DODSON ADDITION TO BROKEN ARROW, TULSA COUNTY, STATE OF OKLAHOMA, ACCORDING TO THE

This Plat of Survey meets the Oklahoma Minimum Standards for the practice of Land Surveying as adopted by the Oklahoma State Board of Registration for Professional Engineers and Land Surveyors.

Bearings shown hereon are based upon a grid bearing of South 88°35'09" West as measured along the South line of Block 1, Dodson Addition to Broken Arrow.

I, Nathaniel J. Reed, a Licensed Professional **Lattil Niv**eyor in the State of Oklahoma, do hereby certify that the above service by the state of the best of my knowledge.

PLAT OF SURVEY Checked By: NJR Proj. No.: 1810 rawn By: NJR

LEGAL DESCRIPTION OF THE REAL PROPERTY

LOT ELEVEN (11), BLOCK ONE (1), DODSON ADDITION TO BROKEN ARROW, TULSA COUNTY, STATE OF OKLAHOMA, ACCORDING TO THE RECORDED PLAT THEREOF.

PROPOSED LEGAL DESCRIPTIONS

TRACT 'A':

THE WEST HALF (W/2) OF LOT ELEVEN (11), BLOCK ONE (1), DODSON ADDITION TO BROKEN ARROW, TULSA COUNTY, STATE OF OKLAHOMA, ACCORDING TO THE RECORDED PLAT THEREOF.

TRACT 'B':

THE EAST HALF (E/2) OF LOT ELEVEN (11), BLOCK ONE (1), DODSON ADDITION TO BROKEN ARROW, TULSA COUNTY, STATE OF OKLAHOMA, ACCORDING TO THE RECORDED PLAT THEREOF.