City of Broken Arrow

Drainage Advisory Committee



CITY OF BROKEN ARROW

OCT 1 5 2019

CITY MANAGER'S OFFICE

APPLICATION

10/14/2019 DATE:

OWNER NAME: PEMBROOKE PARK HOA (HOMEOWNER REPRESENTATIVE: JIM C. JONES)

PHONE NUMBER: 918-231-5029

DEM3BARS@WINDSTREAM.NET **EMAIL ADDRESS:**

OWNER MAILING P.O. BOX 3031 B.A., OKLA. 74013 ADDRESS:

ADDRESS OF PROPERTY WITH

PROPERTY:

IN THE VICINITY OF 3704 WEST BOSTON STREET (NOT A LISTED ADDRESS) DRAINAGE PROBLEM:

NE CORNER POND IN PEMBROOKE PARK'S PARK. ENTER PEMBROOKE PARK LOCATION OF DRAINAGE ISSUE ON FROM OLIVE AVE.; WEST ON W. BOSTON ST. PARK ON NORTH SIDE OF W.

BOSTON ST. ISSUE IS EAST SIDE OF POND'S PERIMETER FENCE.

DESCRIPTION OF PROBLEM:

(*PHOTOS SHOULD ACCOMPANY APPLICATION)

MASSIVE EROSION TO STRUCTURE EAST OF PEMBROOKE PARK'S POND EAST FENCE. SHEAR DROP OF 10-12 FT.; 8 INCHES OF OUR POND'S EAST FENCE. EROSION SLOPES DOWN INTO HAIKEY CREEK TO A DEPTH OVER 18 FT. THE EROSIONS SPANS MORE THAN 70 FT, NORTH & SOUTH ALONG THE WEST SIDE OF HAIKEY CREEK OF WHICH 20-25 FT. FORM A MASSIVE DEEP POCKET RANGING 8 IN. TO ABOUT 4 FT. FROM PONDS FENCE. STREAMS OF WATER FLOW FROM THE EROSIONS WEST BANK DOWN INTO HAIKEY CREEK. TREE CATCHING DEBRIS. HIGH EXTREME HAZARDOUS TO THE PUBLIC.

Will bring Powerpoint/Photos with Presentation

RETURN TO CITY MANAGER'S OFFICE, 220 S. 1ST St. Broken Arrow OK 74012